

SAFETY AIRCRAFT FLIGHT ~~SYSTEM~~ EQUIPMENT

DESCRIPTION

BACKGROUND OF INVENTION

Field of the Invention

5 ~~{0004}~~ The present invention is a computerized security system used to maintain the safe operation of aircraft. ~~The~~ This combined computer system ~~connects~~ utilizes and interconnects to conventional systems and equipment to ~~tracks aircraft, provide an anti-crash system, and an~~ track aircraft, providing an Anti-Crash System with built in anti-tampering system functions. If the flight is

10 interrupted, the ~~anti-tampering system~~ Anti-Crash System further comprises a means to remotely control the aircraft and to detect and avoid aircraft, buildings and ~~other geographic structures~~ geographics.

~~{0002}~~ In the wake of the terrorist events occurring in the United States on ~~Sep.~~ September 11, 2001, our government, the airlines, other institutions,

15 both nationally and abroad and the traveling public recognize the need for a security system to ensure the safety of air travel. Conventionally, aircraft are tracked by means of radar or other signals emitted from the aircraft to receivers at airports, air traffic control centers and military bases. On ~~Sep.~~ September 11, 2001, the signal was tampered with by human intervention, and the planes were lost until

20 the moments of impact with the Twin Towers, the Pentagon and the field in Pennsylvania. Therefore, an onboard ~~anti-tamper system~~ Anti-Crash System that provides an On-Demand-monitoring device is needed to constantly track the position of the aircraft during flight.

~~{03}~~ ~~{0003}~~ On ~~Sep.~~ September 11, 2001, if the air control centers had

25 been able to take control of the planes remotely, or had an Anti-Crash System installed onboard the aircraft the controllers could have steered the planes away

from the ~~Pentagon and~~Pentagon, Twin Towers and could have avoided the field crash in Pennsylvania.

~~[04][0004]~~ During normal operation, a pilot is charged with setting the controls according to the filed flight plan before ~~departing from the gate.~~departure.

- 5 The pilot is ~~and~~ professionally to maintain the course of the flight plan and only to deviate under the direction of the air traffic controllers. Under ~~usual~~certain circumstances, the flight plan is deviated ~~from~~ due to traffic or turbulence. Currently there is not a system to control the plane ~~remote~~ remotely if the captain becomes incapable of piloting the plane. ~~There exist a need for establishing~~exists a need to
10 establish a computer system for ~~remote~~ remotely piloting of the aircraft.

- ~~[05][0005]~~ ~~There also exist a~~ A need currently exists for an anti-crash system ~~for~~Anti-Crash System on aircraft that will prevent crashing into buildings. The aircraft that crashed into the Twin Towers and Pentagon on ~~Sep.~~September 11, 2001 ~~were~~was not equipped with devices to keep them from crashing into
15 buildings and populated areas. Therefore, a sensor system is needed to prevent airplanes from landing or crashing in highly populated areas or in other defined no crash areas, as well as into the no fly zones.

- ~~[0006]~~ Additionally, the system, as previously, mentioned needs to include ~~tamper proof~~ includes anti-tamper technology ~~so that the technology~~
20 ~~cannot be disabled.~~ Current warning systems exist only to alert notify the pilot and/or air traffic controllers ~~control systems when a plane's radar system has been disabled, there are currently no systems to disable the plane's systems if the tracking or piloting systems on the plane are tampered with.~~
Therefore, a need has been established for a tamper proof tracking and
25 navigational system for airplanes.

~~[07]~~ There is a need for retracing or backtracking.

BRIEF SUMMARY OF INVENTION

~~{08}[0007]~~ The present invention is a ~~system~~combined unit of systems ensuring safe aircraft operation. The complete system of the present invention is a ~~security aircraft flight equipment~~, which is made up of components that use sealed navigational computer programs with an ~~anti-tamper system~~functions.

~~{09}[0008]~~ The component parts of the present invention consist of an ~~anti-crash system~~Anti-Crash System (ACS) 20, involving two sub-systems which operate to maintain object distances, such as negative to negative magnets trying to touch. If the ~~anti-crash system~~ Anti-Crash System (ACS) 20 is disabled, the aircraft will not power up for ~~take-off~~departure until all systems are operating. The aircraft to aircraft system is the first of the two sub-systems; it is a fixed system, mounted where a terrorist cannot reach the equipment. The aircraft to building and building to aircraft system is the second of the two systems; buildings that have aircraft monitoring systems send a signal that repels the aircraft from hitting the ~~buildings~~structures. If the building device is tampered with, authorities will be contacted, given ~~with~~ vital information of this event. An early warning device is installed in buildings/structures to signal a potential warning of aircraft invasion--possibly, wired as part of a security alarm.

~~{010}[0009]~~ The second component, an ~~auto-controlling and piloting system~~Auto-Controlling and Piloting System (ACPS) 40, receives commands from the ~~anti-crash system~~, Anti-Crash System (ACS) 20, which overrides, ~~allows the capability to override~~, and takes take over all flight controls of the aircraft by locking out terrorists and/or suicide pilots. These preliminary steps will allow the initiation of the secondary aircraft controller system, if necessary.

~~{011}[0010]~~ The third component, is a ~~monitoring device~~ systemMonitoring Device System (MDS) 30, which sends and receives video, audio, and critical information from the aircraft's flight support equipment, ~~the~~. Along with runway monitoring devices, the building and/or structure monitoring

devices; all information is automatically transferred to the anti-crash system(s) for
analysis. Anti-Crash System (ACS) 20 for analyzing and action.

~~[012][0011]~~ The fourth component, an authorities' security aircraft
flight equipment Authorities' Security Aircraft Flight Equipment (ASAFE) computer
5 50, is securely integrated into the combined systems of all security aircraft flight
equipment. Located within the airports, and proper authorities, such as the FAA,
these on-demand On-Demand systems will allow for full National Security and air
traffic safety.

~~[013][0012]~~ The fifth component, a secondary aircraft controller
10 system, Secondary Aircraft Controller System (SACS) 60, upon security command
commands by FAA or FBI, etc. authorities, ~~giving~~ gives power for remote control of
the distressed aircraft by integrating the ~~SAFE~~ system. For the purpose of
allowing from the integrated Security Aircraft Flight Equipment (SAFE) 10 systems.
This provides safe retrieval of this the distressed aircraft.

15 ~~[014][0013]~~ In short, the present invention includes the following
embodiments described herein to improve flight security from terrorism, or human
error, as well as aircraft equipment deviating outside factory tolerances.

BRIEF DESCRIPTION OF THE DRAWINGS

~~[015][0014]~~ FIG. FIGURE 1 shows an overview of the invention
20 comprising various conventional aircraft related safety systems, ~~and programs,~~
~~and connectivity~~ and their relation required for the present invention.

DETAILED DESCRIPTION OF THE INVENTION

~~[016][0015]~~ The present invention is further detailed below, and this
detailed description includes an overview outline section, an explanation of the
25 present invention applied to actual scenarios, and lastly a summary of aircraft
crashes which is referenced earlier in the Detailed Description.

~~[0016]~~ Aircraft Systems Interface 11

Electrical connections tying all of the conventional systems to the "SAFE" system.

~~[018][0017]~~ (Safe System)

- ~~[019][0018]~~ The Aircraft System Interface will allow the "SAFE" system ~~10~~ 10 systems to act together harmoniously with the primary aircraft, other aircraft, ground control, and designated security authorities. The scenarios noted within are both; real life and predicted. These scenarios were taken into consideration when designing the "SAFE" system ~~10~~ 10 systems. The Aircraft Systems System Interface ~~40~~ 11 will be listed in the following sections: Power
- 10 Plants & Airframe, Electronics, and Mainframe.

~~[020][0019]~~ Power Plants & Airframe

~~[021][0020]~~ A) Auto Pilot (AP)

~~[022][0021]~~ 1) Variable/increased flight adjustment capabilities

~~[023][0022]~~ 2) Increase of: thrust/pitch/yaw movements

15 ~~[024][0023]~~ B) Collision Avoidance System (CAS)

~~[025][0024]~~ 1) Outside input, such as transponder from high buildings, other aircraft, etc.

~~[026][0025]~~ 2) Onboard anti-collision radar

~~[027][0026]~~ C) Aircraft Mechanical System (AMS)

20 ~~[028][0027]~~ 1) Flight controls

~~[029][0028]~~ 2) Power plants controls

~~[030][0029]~~ D) Aircraft Electrical Systems (AES)

~~[031][0030]~~ 1) Power plant generators

~~[032][0031]~~ 2) Emergency generator system

25 ~~[033][0032]~~ E) Onboard, Air to Air Refueling (AAR)

~~[034][0033]~~ 1) Retractable, external refueling probe

~~[035][0034]~~ F) Expansion Capabilities

~~[036][0035]~~ 1) For future contingencies, both hardware & software

~~[037][0036]~~ Aircraft Systems Interface

| | | |
|----|-----------------|---|
| | | {038}{0037} -(Safe System) |
| | | {039}{0038} Electronics |
| | | {040}{0039} A) Aircraft Radio Systems (ARS) |
| | | {041}{0040} 1.1) All communications systems, onboard and beyond |
| 5 | aircraft | |
| | | {042}{0041} 2.2) Both audio visual to remote receivers |
| | | {043}{0042} B) Transponder |
| | | {044}{0043} 1.1) Sending unit for identification and location |
| | | {045}{0044} C) Sensors <u>sensors</u> |
| 10 | | {046}{0045} 1.1) Instrumentation for monitoring engine characteristics |
| | | {047}{0046} 2.2) Instrumentation for monitoring airframe |
| | characteristics | |
| | | {048}{0047} D) Onboard Recording System (ORS) |
| | | {049}{0048} 1.1) Collecting all voice & Video input, onboard |
| 15 | | {050}{0049} E) Black Box |
| | | {051}{0050} 1.1) Flight Data Collection |
| | | {052}{0051} F) Navigational Systems (NS) |
| | | {053}{0052} G) Topographical Analysis System (TAS) |
| | | {054}{0053} 1.1) Feeds topographical data into the navigational |
| 20 | system | |
| | | {055}{0054} Security Aircraft Flight Equipment (SAFE) |
| | | {056}{0055} 1.A) Anti-Crash System (ACS) <u>20</u> |
| | | {057}{0056} a.1). aircraft to aircraft |
| | | {058}{0057} b.2). aircraft to building, building to aircraft |
| 25 | | {059}{0058} 2.B) Auto Controlling and Piloting System (ACPS) <u>40</u> |
| | | {060}{0059} 3.D) Monitoring Device System (MDS) <u>30</u> |
| | | {061}{0060} a.1) <u>aircraft</u> |
| | | {062}{0061} b.2) <u>runway</u> |
| | | {063}{0062} c. 3) <u>structure(s)</u> |

~~[064][0063]~~ 4. E) Authorities' Security Aircraft Flight Equipment
System ~~(ASAFES)~~ (ASAFE) System

~~[065][0064]~~ 5. F) Secondary Aircraft Controller System (SACS) 60

~~[066][0065]~~ Aircraft Systems Interface (Safe System) Main Frame

5 ~~[067][0066]~~ The "Main Frame" component will have at least three
areas of data collection and command outputs, along with room for expansion in
the hardware and software. The "Main Frame" may be included into the Aircraft
Systems through one or more file servers; that interface with all onboard systems
(Aircraft Systems Interface).

10 ~~[068][0067]~~ A) Anti-Crash System

~~[069][0068]~~ 1. 1) Aircraft System Interface

~~[070][0069]~~ 2. 2) Auto Control and Piloting System

~~[071][0070]~~ a) 3) Enhancement module

~~[072][0071]~~ B) Security Interface

15 ~~[073][0072]~~ 1. 1) Authorities Security Aircraft Flight Equipment
Program

~~[074][0073]~~ 2. 2) Thumb Print Reader

~~[075][0074]~~ 3. 3) Security Code Key Pad

~~[076][0075]~~ 4. 4) Pilot Security Key

20 ~~[077][0076]~~ 5. 5) Monitoring Device System (MDS) 30, multiple
sources, (i.e. audiovisual)

~~[078][0077]~~ 6. 6) Any additional Security devices or systems to be
included at a future time

~~[079][0078]~~ C) Secondary Aircraft Controller System (SACS) 60

25 ~~[080][0079]~~ 1. 1) Allows two ACS to interface, i.e. aircraft to aircraft
remote flight capabilities

~~[081][0080]~~ Security Aircraft Flight Equipment and Technologies
Aircraft: Anti-Crash System (ACS) 20, Monitoring Device ~~Systems~~ System (MDS)
30, Auto Controlling and Piloting System (ACPS) 40, ~~Software Programs,~~ software

~~programs, Solid State Computer, solid-state computer, technologies, such as,~~
~~PROM, ROM, and etc. Modem, modem, Monitor, monitor, Keypad, eyepad,~~
~~Thumb Scan, thumb scan, Print Port Dongle, port dongle, Pilot's pilot's~~
~~personalized flight keys, Transponders, transponders, Global Phone, global phone,~~
5 ~~Sensors, sensors, Cameras, cameras, Lighted Alarm Buttons, lighted alarm~~
~~buttons, Flash Card flash card reader and writer unit (for mapping to back track),~~
~~Microphone, microphone, Speakers speakers~~

~~[082][0081] Structure: (Building, Bridges, Monuments, etc.), Anti-~~
~~Crash System (ACS) 20, Monitoring Device Systems (MDS) 30~~
10 ~~[083][0082] Software Programs, software program, Solid State~~
~~Computer, solid-state computer, technologies, such as, PROM, ROM, and etc. Etc.~~

~~[084][0083] Modem, modem, Monitor, monitor, Print Port Dongle,~~
~~port dongle, Transponders, transponder, Global Phone, global phone, Sensors,~~
~~sensors, Cameras, cameras, Optional: Warning Horn optional warning horn~~
15 ~~[085][0084] Airports: Anti-Crash System (ACS) 20, Monitoring Device~~
~~System (MDS) 30, Computer Runway Monitors: Transponders computer runway~~
~~monitors: transponder, Secondary Aircraft Controller System (SACS) Authorities'~~
~~Security Aircraft Flight Equipment (ASAFE.)~~

~~[086][0085] Anti-Crash System (ACS) 20, Monitoring Device Systems~~
20 ~~System (MDS) 30, Software Programs, software program.~~

~~[087][0086] Solid State High End Computer, solid-state high end~~
~~computer, technologies, such as, i.e., PROM, ROM, and etc.~~

~~[0087] Virtual Reality Ability and equipment, Modem, Monitor, Control~~
~~Panel, Keypad, Thumb Scan, Print Port Dongle, Pilot's personalized flight keys,~~
25 ~~Transponders, Global Phone, Sensors, Microphone, Speakers~~

~~[088][0087] Authorities' Security Aircraft Flight Equipment (SAFE)~~
~~Computer (ASAFE) computer Monitoring Device Systems System (MDS) 30~~
~~Software Programs, software program, (with ON-DEMAND Command Device)~~

also, with ~~Networked Rights~~, network rights, ~~Solid-State Computer~~, solid-state computer, technologies, such as, i.e., PROM, ROM, and etc.

[0088] ~~Modem, modem, Monitor, monitor, Keypad, keypad, Thumb Scan, thumb scan, Print Port Dongle, port dongle, Proprietary Personalized Key,~~
5 proprietary personalized key, Transponders, transponder, Global Phone, global phone, Microphone Speakers, microphone speakers, All Units all units are supplied with an independent power backup if one is not already provided.

Secondary Aircraft Controller System (SACS) 60

[0089] Anti-Crash System (ACS) 20, Monitoring Device System
10 (MDS) 30, Auto Controlling and Piloting System (ACPS) 40 software program, solid-state computer, technologies, such as, PROM, ROM, etc. modem, monitor, keypad, thumb scan, port dongle, pilot's personalized flight keys, transponder, global phone, sensors, cameras, lighted alarm buttons, flash card reader and writer unit (for mapping to backtrack). microphone, speakers virtual reality ability
15 and equipment, modem, monitor, control panel, keypad, thumb scan, port dongle, pilot's personalized flight keys, transponder, global phone, sensors, microphone, speakers.

[091][0090] *Service Technicians:* Service Technician dongle/key, programmed with a master license dedicated for servicing only-service not flight.

20 [092][0091] *Security Aircraft Flight Equipment System Each Aircraft(SAFE) 10 systems* Each aircraft comes with an optional backup Security Aircraft Flight Equipment (SAFE) 10 systems System-10 in place. This The backup system has the same capabilities as the master system. While in idle its only function is to collect information. Due to any given malfunction, the backup
25 Security Aircraft Flight Equipment (SAFE) System-10 systems would automatically activate. It would immediately advise appropriate personnel of a problem with the master backup Security Aircraft Flight Equipment (SAFE) 10 systems System.

~~[093][0092]~~ *Anti-Crash System (ACS) 20* This system is active at all times; the functions are collecting, analyzing and processing data, as well as allocating and dispersing assigned duties to other portions or units of the Security Aircraft Flight Equipment (SAFE) ~~10-system~~ systems. The only time the Anti-Crash System (ACS) 20 would be in a shut down mode is for servicing. [Refer to the Service Technician section.] The Anti-Crash System (ACS) 20 is the component that utilizes the perimeters set by manufacturers, navigational technicians, authorities, crews etc. for the aircraft to follow. It is receiving data from onboard control systems and any other sensors (displays, gauges, selectors, indicators, and other apparatus, etc.). Sensors 160 can be added for the indication of excessive vibration and connected through the Security Aircraft Flight Equipment (SAFE) ~~System-10~~ systems. The Anti-Crash System (ACS) 20 identifies any fluctuation that is outside the manufacturer tolerances and safety specifications. By the emitting and receiving of signals the aircraft will identify the presence of other Anti-Crash System (ACS) 20 and Monitoring Device System (MSD) 30 apparatuses. This allows the aircraft to veer from solid objects, such as other planes, buildings, bridges, and monuments. Due to the settings of perimeters within the mapping program for designated 'no fly zone areas'; an aircraft will not be able to fly into a protected environment. These areas are set for national security and flight safety.

~~[094][0093]~~ The peripherals are external devices connected to the computer, (such as conventional keypad and thumb print scanners). For the security of the aircraft, concealed ~~conventional~~ dongle keys are used for the Security Aircraft Flight Equipment System (SAFE) ~~10 licensees~~ systems license only. A second ~~conventional~~ dongle or chip key is necessary for the operation to initialize the aircraft for flight by the pilot. This is called a pilot's personalized flight key. This key will only be licensed and registered to the pilot, with thumb print identification programmed into the chip.

~~[095][0094]~~ The Anti-Crash System (ACS) 20 copies all necessary information of the flight plan to a flash card. In the ~~event~~case of an equipment malfunction caused by atmospheric disturbances, the aircraft has the ability to backtrack. ~~The~~This backtrack system is used by the Anti-Crash System (ACS) 20 and the Auto Controlling and Piloting System (ACPS) 40. These systems have usage of the ~~backtrack~~backtracking card independently. Upon receiving a transmission from another aircraft, through the Secondary Aircraft Controller System (SACS) 60, the Anti-Crash System (ACS) 20 will recognize and work simultaneously with an external Anti Crash System (ACS) 20 (i.e. chase aircraft).
10 The Anti-Crash System (ACS) 20 will make the corrections, overrides manual piloting, for safe flight, landing, and liftoff. ~~The crew can opt to use this system at their discretion.~~

~~[096][0095]~~ Each portion of the ~~SAFE(10) system~~Security Aircraft Flight Equipment System (SAFE) 10 systems receives the demands from the Anti-
15 Crash System (ACS) 20, telling it what its job is. The Anti-Crash System ACS 20 has the capability to override or lock out the manual controls and/or existing ~~Auto Pilot~~Auto-Pilot (AP) 80. The Anti-Crash System (ACS) ~~ACS~~ 20 interfacing with Auto Pilot (AP) 80 can recalibrate the aircraft for total computer jurisdiction. The computer part of the ~~Anti-Crash System (ACS) 20~~Auto Controlling and Piloting
20 System (ACPS) 40 would have override capabilities such as, landing gear. The Anti Crash System (ACS) 20 will allow for the ~~Auto Pilot (AP) 60~~Auto Controlling and Piloting System (ACPS) 40 to take over control of the aircraft's flight systems for maneuverability. ~~[0096] The Auto Crash System (ACS) 20 will be linked to all the controls for override: (1) to force a terrorist/pilot to relinquish command, (2) for~~
25 ~~the Secondary Aircraft Controller System (SACS) 60 to override the aircraft, by acting harmoniously with the rest of the systems in the SAFE 10 system. Refer to Equipment Usage and Synopses Scenarios #ALL especially 1, 25~~

~~[097][0096]~~ Auto Controlling and Piloting System (ACPS) ~~The Auto Controlling and Piloting System 40~~ makes corrections, overrides manual piloting,

for safe flight/landing/lift-off ~~flight/landing/lift-off~~ because the Security Aircraft Flight Equipment (SAFE) System ~~10~~ regulates it necessary. The pilot also can opt to use this provision. The ~~ACPS~~ Auto Controlling and Piloting System (ACPS) 40 is a device module that enhances the existing Auto Pilot 80. It is also controlled by the
5 Anti-Crash System 20. The (ACPS) 40 is a device module that enhances the existing Auto Pilot 80. It is also controlled by the Anti-Crash System 20.

~~{098}{0097}~~ This portion of the Security Aircraft Flight Equipment ~~(SAFE) System (SAFE) 10 systems~~ receives the demands from the Anti-Crash System (ACS) 20 telling it what its job is. This system has the power to override or
10 lock out the manual controls and/or existing Auto-Pilot Autopilot (AP) 80, recalibrating the aircraft for total computer jurisdiction. The computer part of the Auto Controlling and Piloting System (ACPS) 40 would have the control over the landing gear. This is allowing for the Auto Controlling and Piloting System (ACPS) 40 to take over control of the aircraft's flight systems, (landing gear, flaps, etc.)

15 ~~{099}~~ The Auto Controlling and Piloting System (ACPS) 40 will be linked to all the controls for override protection: (1) to force a terrorist/pilot to relinquish command; (2) for the Secondary Aircraft Controller System (SACS) 60 to override the aircraft, by acting harmoniously with the rest of the units in the Security Aircraft Flight Equipment (SAFE) ~~10-System systems~~. Refer to Equipment
20 Usage and Synopses Scenarios #3, 5, 12-15, especially 21, 28, 39

~~{0400}{0099}~~ *Monitoring Device System (MDS) 30* The Monitoring Device System (MDS) 30 has the programming with commands of ~~On-Demand~~ On-Demand 230 live video and audio, ~~the-these~~ video and audio devices are not constantly recording. The Monitoring Device System (MDS) 30 includes
25 peripherals to be activated in three ways: (1) automatically by the Anti-Crash System (ACS) 20, (2) manually by alarm devices and sensors 160, and (3) by appropriate authorities.

~~{0401}{0400}~~ Aircraft The ~~On-Demand~~ On-Demand Monitoring Device System (MDS) 30 consists of cameras, audio speakers and receivers, phone,

alarm devices and sensors. The aircraft is setup with several manual alarm devices in the fuselage and cockpit. The peripheral adapters for an aircraft Monitoring Device System (MDS) 30 work both ways in transmitting and receiving signals/data. First, the unit sends the vital information that the Anti-Crash System (ACS) 20 collected from the aircraft's flight support equipment. This includes registration information, longitude, latitude, altitude, compass heading, etc. Secondly, it retrieves data from the Structure Monitoring Unit and the Runway runway Monitoring Devices. ~~And thirdly,~~ Thirdly, it sends and retrieves data from the Authorities Security Aircraft Flight Equipment ~~(SAFE) 10 Computer(ASAFE)~~ System 50 computer 190. (Reference number 190 represents computer programs or software. Reference number 200 represents speakers, cameras, microphones, and sensing equipment. Reference number 230 represents a peripheral, such as described above.)

~~[0102][0101]~~ The vital information accumulated by the Monitoring Device System (MDS) 30 is automatically transferred to the Anti-Crash System (ACS) 20 for ~~analyzation~~ analyzing. The Anti-Crash System (ACS) 20 will then systematically activate the appropriate systems ~~to take the necessary action to resolve the issue. The conventional Airport Runway Monitoring Devices, send signals to the ACS 20, allowing the ACS 20 to compensate the aircraft for all~~ corrections necessary for a safe landing/take off. Refer to Equipment Usage and Synopses Scenarios #ALL especially 3, 26, 44

~~[0103][0102]~~ Airport Runway-runway Monitoring Devices These these devices send signals through the Monitoring Device System (MDS) 30 to the Anti-Crash System (ACS) 20. Allowing the Anti-Crash System (ACS) 20 to compensate the aircraft for all corrections necessary, in order for it to make an accurate approach/landing and/or takeoff. Refer to Equipment Usage and Synopses Scenarios #3, 6, 7

~~[0104][0103]~~ Referring next to the Authorities' Security Aircraft Flight Equipment (ASAFE) 50 (ASAFES) Computer computer This 190, this computer

system is developed for ground authorities such as FAA, Air Traffic Control, Airline company, FBI, etc., to help with National Security and air traffic flight safety. At any given time the appropriate authorities would have ~~On-Demand Live Video~~ On-Demand live video and audio, both for transmitting and receiving signals, even if there is no apparent problem. The computer will receive and display all data (from multiple airplanes) at any given time. From this system, the proper authorities will be able to activate any particular aircraft's Monitoring Device System (MDS) 30, to collect the data and view activity on the aircraft. It also gives more support in verbal contact with the pilot. Navigational data is received and sent for approval.

[0105][0104] Note: Potentials, through the Security Aircraft Flight Equipment System (SAFE) ~~system~~ 10 systems working with GPS and possible radar will allow airlines to monitor the location of their aircraft at all times (tracking device) Note: each ~~authority's~~ Authorities' computer will be designed for each specific function. This is an existing computer technology. Refer to Equipment

Usage and Synopses Scenarios #3,4,5,9,46

[0106][0105] *Secondary Aircraft Controller System (SACS) 60*. The Secondary Aircraft Controller System (SACS) 60 equipment is energized by a specialized licensed key. After the implementation of the key, three codes are necessary from three separate organizations to ~~active~~ activate the Secondary Aircraft Controller System (SACS) 60. Upon arriving to the distressed aircraft, the Secondary Aircraft Controller System (SACS) 60 emits codes to the Security Aircraft Flight Equipment (~~SAFE~~) System (SAFE) 10 systems, thereby identifying each other. After transmission is complete and approval has been documented, the Secondary Aircraft Controller System (SACS) 60 may take possession and control of the aircraft, through computer technology.

[0107][0106] The Secondary Aircraft Controller System (SACS) 60 is a computer with peripheral attachments: simulator control panel, display monitor and cameras aboard a separate airplane within visual distance.

~~[0108][0107]~~ Note: The Secondary Aircraft Controller System (SACS) 60 pilot has vision and the controls comparable to Virtual Reality piloting, he is sitting and controlling the distressed aircraft. Refer to Equipment Usage and Synopses Scenarios #9,12,13,34

5 ~~[0109][0108]~~ *Secondary Aircraft Fuel Tanker* The Anti-Crash System (ACS) 20 detects low fuel and it sends the Monitoring Device System (MDS) 30 a message to contact the proper authorities about the problem. At that time, the authorities can send up the Secondary Aircraft Fuel Tanker (SAFT) 60 to provide the necessary fuel or assistance. Once they ~~have gotten~~ are within a designated
10 range, the two ~~aircrafts~~ airplanes Anti-Crash Systems (ACS) 20 and Monitoring Device Systems 30 work ~~together and maneuver together to complete for~~ completion of the refueling process and whatever task the Secondary Aircraft Fuel Tanker (SAFT) 60 ~~were was~~ sent up to perform. Also as the Secondary Aircraft Fuel Tanker (SAFT) 60 approaches a distressed aircraft, due to a special license,
15 the two Anti-Crash Systems (ACS) 20 identify and link together. This holds each aircraft at bay for precise tracking. This ~~totally eliminates pilot error, therefore~~ enhancing accuracy during refueling that is necessary in emergency operation ~~and it enhances accuracy during the refueling process.~~ Refer to Equipment Usage and Synopses Scenarios #24

20 ~~[0110][0109]~~ The Security Aircraft Flight Equipment (~~SAFE~~) System (SAFE) 10 (Structures, Buildings, etc.) Only two systems are required for the structure to be completely protected by the Security Aircraft Flight Equipment (SAFE) System 10; the Anti-Crash System (ACS) 20, and the Monitoring Device System (MDS) 30. A power backup unit will be provided if not already existing
25 within the structure.

~~[0111][0110]~~ *Anti-Crash System (ACS) 20* Ground Structures: This Anti-Crash System (ACS) 20 prevents aircraft ~~for~~ from crashing into ground structures such as buildings, bridges, and monuments. The Anti-Crash System (ACS) 20 beacons emit two independent perimeter signals. ~~As being the brains of~~

~~any operation it allocates duties to the Monitoring Device System (MDS) 30. Refer~~
to Equipment Usage and Synopses Scenarios #39, 41, and 42

~~[0112][0111] Monitoring Devices-Device System (MDS) 30~~ Ground
Structures: The Monitoring Device System (MDS) 20 in a building is a computer
5 with peripherals. The cameras, motion detectors/sensors are the peripherals
connected to the computer. These are only for the security of the Security Aircraft
Flight Equipment (SAFE) System 10. The telephone connections and warning
alarms are to help in the safety of the community. It would be optional to connect
to any existing security systems, if desired. Refer to Equipment Usage and
10 Synopses Scenarios #39, 41, and 42

~~[0112]~~Registration: ownership, registration number, year, make,
model, and series, body type, Vin number, etc. Refer to Equipment Usage and
Synopses Scenarios #31, 47

~~[0114][0113] Service Technicians: The Service Technicians"~~
15 Technicians dongle/key is individually coded, that gives proprietary authorization
for repairs and installation of the Security Aircraft Flight Equipment System (SAFE)
10. This will not commission the service technician the rights for aircraft flight
status. Due to the need for high security, this would only allow a secured service
technician to install ~~any and all~~ any/all software perimeters and licenses, on all
20 Security Aircraft Flight Equipment System (SAFE) 10 equipment. Refer to
Equipment Usage and Synopses Scenarios #48

~~[0115][0114] Presidential Override~~ This is a code that overrides
everything EXCEPT the Anti-Crash System (ACS) 20. Refer to Equipment Usage
and Synopses Scenarios #2, 34

25 ~~[0116][0115] Equipment Usage In Synopses Scenarios~~ The following
synopses scenarios explain how the present invention interfaces with existing
conventional aircraft systems to optimize the safe operation of an aircraft. In each
scenario presented below, a problem has occurred with an aircraft. The present

invention in conjunction with conventional aircraft components are explained as to how the situation can be avoided in the future utilizing the present invention.

[0117][0116] 1) SOMEONE TAMPERS WITH THE AIRCRAFT OPERATING SYSTEM WHILE ON THE GROUND. If someone has tampered with any part of the operating system or there is a malfunction in the operating system, then the Anti-Crash System (ACS) 20 will trigger a shutdown not allowing the turbines and/or the engines to function. This cannot be overridden by resetting the equipment. The Security Aircraft Flight Equipment (SAFE) 10 ~~system works~~ systems work in conjunction with the onboard diagnostic process. In an event that a signal is sent notifying of a problem, it will disable the aircraft for flight. This will notify all necessary ground authorities of the situation through the Monitoring Device System (MDS) 30. The data sent will include the time and location of the problem in the administrative device management program. Reference: Actual Crash Document # 12, 13, 20, 26, 27, 28, 31, 34, 36, 40, 42, 46, 52, 66, 69, 70, 73, 74, 76, 78

[0118][0117] 2) A PASSENGER ENTERS INTO THE AIRCRAFT FLIGHT DECK (COCKPIT) WHILE THE PLANE IS STILL ON THE GROUND. In the event of an unauthorized person entering into the flight deck (cockpit) while on the ground, ~~The~~ the Monitoring Device System (MDS) 30 will be activated automatically by the Anti-Crash ~~Systems~~ System (ACS) 20. This system will send pictures and data to designated parties. Now the Anti-Crash ~~Systems~~ System (ACS) 20 would put the aircraft in a standby mode. In order to release the aircraft for flight, a multiple code by several independently located specified individuals must be entered. An example is using the pilot, airline security, FAA, FBI etc.; using as many codes as desired.

[0119][0118] 3) AIR TRAFFIC CONTROLLERS (ATC)/PILOT'S SITUATIONS. ~~(crashes~~ Crashes and close calls) Here are some actual scenarios causing near misses or crashes, due to (ATC)/Pilot's error.

[0120][0119] A TC:

[0121][0120] 1. Dispatched inadvertently for takeoff/landing on a runway that was closed or ~~down~~down for repair.

[0122][0121] 2. Directed Directing in and out bound aircraft onto the same runway.

5 [0123][0122] 3. Directs Directing multiple planes to the same vectors causing a mid-air crash.

[0124][0123] 4. Aircraft impacted impacts terrain after being given an improper vector by ATC.

10 [0125][0124] 5. Authorized flight, ~~to~~ descend below altitude causing mishaps.

[0126][0125] Pilot's:

[0127][0126] 1. Ignoring ATC instructions.

[0128][0127] 2. Ignoring warning signals and devices

15 [0129][0129] 4. Over ~~corrections~~ correcting and inability to act quick enough quickly

[0130][0128] 3. Misinterpreted communication between ~~(ATC and pilot)~~ ATC and pilot.

[0131][0130] 5. They neglect to post a warning when they find a dangerous mechanical ~~problems~~ problem.

20 [0132][0131] Note: The Federal Aviation of Administration, National Transportation Safety Board. States, "Pilots are blamed in 37% of all serious airline accidents, ~~well~~ while other persons ~~person~~, such as a mechanic or controller, is are blamed in 39%". A description of more than 46,000 aviation accidents is located at www.nts.gov. More detailed lists are located at www.airdisaster.com
25 and www.crashdatabase.com. The ~~authorities'~~ Authorities' Security Aircraft Flight Equipment ~~(SAFE)~~ (ASAFE) System ~~10~~ in the Control Tower also has two additional programs, an airport mapping configuration, and a ~~ground-plotting~~ ground-plotting program. The runway Monitoring Devices System (MDS) 30 ~~are~~ is also connected to ~~that~~ the Security Aircraft Flight Equipment (SAFE) 10-system

systems. Airports utilizing these two programs, coupled with the complex marriage in the Security Aircraft Flight Equipment (SAFE) 10 systems now will virtually eradicate the current close calls, and crashes caused by human error in departure and arrival, as well as in taxiing procedures. The capabilities of the program will
5 now allow the Air Traffic Control Tower personnel (ATC) to input the data for a specific taxi course that the Captain must follow. It also allows them to monitor all ground movement of aircraft.

[0133][0132] A direct link to any specific plane is made by the Security Aircraft Flight Equipment (SAFE) ~~system~~ 10 systems, collecting pertinent
10 data about the aircraft. The Anti-Crash System (ACS) 20 on the aircraft, as in flight, will identify each aircraft's location, and not allow aircraft to collide while on the ground during a taxi procedure. ~~Also,~~ In addition, it will not allow for two aircraft to enter the same runway on a departure and arrival situation, or enter each other's airspace.

15 [0134][0133] Note: At the time of a mechanical malfunction, the proper authorities will be notified through the Monitoring Device System (MDS) 30. Reference: Actual Crash Document # 23, 32, 34, 35, 37, 44, 48, 52, 53, 54, 55, 60, 61, 62, 63, 64, 65, 68, 71, 81, 82, 84

[0135][0134] 4) THE WRONG LAT./LONG. IS PLOTTED AND THE
20 AIRCRAFT IS SET TO CRASH INTO A MOUNTAIN (course is plotted while still grounded) Let's say, a course is plotted and this course has an error in it, or a hijacker, or suicidal pilot attempts a crash course. FIRST, the Security Aircraft Flight Equipment (SAFE) ~~system~~ 10 recognizes ~~10 systems recognize~~ the data sent from the plotting equipment. If this would result in a collision, a warning alarm
25 will sound. SECOND, The Anti-Crash System (ACS) 20 will not allow the aircraft to power up, until corrections are made in the plotted course. In this scenario, the Monitoring Device ~~apparatus~~ System (MDS) 30 will upon any of the above attempts, automatically alert ground authorities, FAA, etc. This will help to ensure

greater success in the air traffic safety efforts. Reference: Actual Crash Document # 3, 11, 30, 33, 48, 68, 71

[0136][0135] 5) AN INCORRECT COURSE IS PLOTTED IN THE AIR AND THE AIRCRAFT IS SET TO CRASH INTO A MOUNTAIN Let's say, a course is plotted and this course has an error in it, or a hijacker, or suicidal pilot attempts a crash course. FIRST, the Security Aircraft Flight Equipment (SAFE) system ~~10 recognizes~~ 10 systems recognize the data sent from the plotting equipment. If this would result in a collision, a warning alarm will sound. SECOND, The Anti-Crash Systems (ACS) 20 will not allow the aircraft to deviate from the original plotted course, until corrections are made in the new plotted course. In this scenario, the Monitoring Device System (MDS) ~~20-30~~ will, upon any of the above attempts, automatically alert ground authorities, FAA, etc. This will help to ensure greater success in the air traffic safety efforts. Reference: Actual Crash Document # 3, 11, 30, 33, 48, 68, 71

15 [0137][0136] 6) A PILOT TRIES TO CRASH THE AIRCRAFT DURING LIFTOFF OR UPON LANDING This scenario brings to mind the act of pilot suicides or terrorist(s). The first thoughts are for the safety of the passengers and ~~crew members~~ crewmembers; also saving the airplane.

[0138][0137] Monitoring Device System (MDS) 30 components installed at the end of each airfield runways ~~transmits~~ transmit signals for the use of lift off attempts and approach landings. To give you more detail of this event, data is sent from the ~~monitoring devices~~ Monitoring Devices on the runway to the computer in the plane, ~~telling~~ Telling the exact angle, (in degrees for line up), giving the exact length, (from the beginning to the end of the runway), so that the aircraft would not over shoot the runway. Also information of the altitude of the aircraft from the runway, so that the aircraft would not crash. The systems being linked will allow the data in the registration (~~SAFE~~ Security Aircraft Flight Equipment (SAFE) 10 registration, see below) from any particular plane to be

utilized. These systems work as one unit in sharing of data. Such data would be of air speed, RPM and how much distance the aircraft needs for takeoff or land, etc.

~~[0139][0138]~~ NOTE: In the process of ~~liftoff~~; If lift off, a pilot does not reach the speed necessary to ~~liftoff~~ lift off safely, the Anti-Crash ~~Systems~~ System

5 (ACS) 20 would do one of two things.

~~[0140][0139]~~ 1: It would abort the liftoff by engaging the Auto Controlling and Piloting (ACPS) 40 portion of the system. This system would reverse the thrust and apply the brakes, bringing the plane to a safe stop. As this would occur, the Monitoring Device System (MDS) 30 on the aircraft will make
10 connection with specified authorities on the ground.

~~[0141][0140]~~ 2: The aircraft ~~data base~~ database check, "all is a go" but the pilot did not power up enough. The Anti-Crash ~~Systems~~ System (ACS) 20 would, before reaching the point of no return, engage the Auto Controlling and Piloting System (ACPS) 40 portion of the system. It would power up and initiate
15 ~~liftoff~~ lift off, notifying the ground authorities that there is a problem, so that the pilot can be contacted.

~~[0142][0141]~~ NOTE: In the process of landing; If the pilot "comes in too short", the Anti-Crash Systems (ACS) 20 will receive data sent from the runway Monitoring ~~Devices~~ Device System (MDS) 30 located on a specified
20 runway. The data sent tells the position of the aircraft in conjunction with the runway; angle in degrees, the altitude, air speed, distance of landing, etc. If the pilot does not fix his course to the proper approach, ~~The~~ the Anti-Crash ~~Systems~~ System (ACS) 20 will implement the Auto Controlling and Piloting System (ACPS) 40, to make necessary corrections.

25 ~~[0142]~~ NOTE: Upon landing; The pilot misjudges the runway and "comes in too long" (over shoots the runway). As we talked above, there is data sent from the runway Monitors ~~Devices~~ Device System (MDS) 30 to the Anti-Crash ~~Systems~~ System (ACS) 20, this will inform the pilot of an error in his approach. If the pilot does not correct the error, then the Auto Controlling and Piloting System

(ACPS) 40 will come into action. The Security Aircraft Flight Equipment (SAFE) ~~system-10 systems~~ will ~~gage-gauge~~ the situation, abort the landing, and power up the aircraft. The Auto Controlling and Piloting System (ACPS) 40 will go into a holding pattern.

5 [0144][0143] NOTE: The pilot is on the wrong approach; His compass bearing doesn't line up with the runway. In this case the Anti-Crash ~~Systems-System~~ (ACS) 20 will activate the Auto Controlling and Piloting (ACPS) 40 portion of the system, ~~power up, and enter by powering up the aircraft and entering~~ into a holding pattern. Waiting for a command from an Air traffic controller
10 (ATC).

 [0145][0144] NOTE: In the event that the aircraft is coming in out of improper plane (not level). The Anti-Crash ~~Systems-System~~ (ACS) 20 will read the data coming from the onboard deck equipment. Upon making connection with the Auto Controlling and Piloting System (ACPS) 40, the aircraft will make adjustment
15 to compensate the aircraft to a level position. This adjustment would only be used in a landing procedure. Reference: Actual Crash Document # 2, 5, 6, 10, 11, 15, 18, 24, 25, 26, 29, 30, 36, 37, 40, 41, 43, 45, 46, 48, 51, 65, 67, 72, 84

 [0146][0145] 7) WHAT STOPS THE AIRCRAFT FROM CRASHING INTO THE AIRPORT BUILDINGS, TERMINALS, HANGERS, CONTROL
20 TOWERS UPON LIFTOFF OR LANDING? (Example: ~~of a possible~~ suicide pilot or terrorist) Before the aircraft reaches the point of collision with any building(s) at an airport, the Anti-Crash ~~Systems-System~~ (ACS) 20 would power down the aircraft, thereby softening the collision or stopping it altogether. In the event that the aircraft has already taxied out onto the runway or an aircraft has landed onto the runway,
25 ~~the~~ The runway Monitoring ~~Devices-Device~~ System (MDS) 30 are in contact with the Anti-Crash ~~Systems-System~~ (ACS) 20; these systems would not allow the aircraft to waiver off course from the runway. The Auto Controlling and Piloting System (ACPS) 40 portion is activated through the same connection, as well as receiving information about the engines RPM. If the aircraft RPM are running too

high for a safe landing, it will void the landing. If the aircraft RPM are running to low for takeoff, then it will abort takeoff or increase the thrust for takeoff. The aircraft will be forced to go into a holding pattern. Reference: Actual Crash Document # 18, 46

5 [0147][0146] 8) A BOMB OR A BOMBER IS ON THE PLANE In the event of a situation involving a bomb or bomber the aircraft has been fitted with silent alarm devices. These devices are located in several places throughout the fuselage area. This gives security to the flight attendants and pilots with the ease of accessibility to the alarm equipment. Once a silent alarm device has been
10 triggered, it automatically locks in the Monitoring Device System (MDS) 30 portion of the system, alerting those in the flight deck (cockpit) and the appropriate authorities. The information transmitted advises them of a serious situation that is occurring on the aircraft. This will allow the flight attendants' hands to be free so they can assist other members in dealing with the situation. (Example; shoe
15 bomber.) Reference: Actual Crash Document # 16

 [0148][0147] 9) A HIJACKER, TERRORIST AND/OR UNAUTHORIZED PERSON GETS INTO THE AIRCRAFT FLIGHT DECK (COCKPIT) WHILE IN FLIGHT In the event of an entry into the aircraft flight deck (cockpit), again the monitoring cameras would send pictures and data through the
20 Monitoring Device System (MDS) 30 to the designated parties. This will allow the FBI and/or FAA to determine the severity of the existing situation, as well as, give them insight of how to respond. Their responses could include everything from ignoring the situation, allowing the pilot to handle the situation, or to take control of the aircraft. In the event that they would deem it necessary to implement one of the
25 other parts of the Security Aircraft Flight Equipment (SAFE) 10 ~~systems~~systems, they would need to use; three individual parties, set up at independent locations to enter their separate codes. This enables them access to the Auto Controlling and Piloting System (ACPS) 40 and/or the Secondary Aircraft Controller System (SACS) 60.

[0149][0148] Note: When necessary, the proper authorities will implement the Secondary Aircraft Controller System (SACS) 60. This system allows a security type aircraft that is within visual distance to take total control. They will pilot and land the aircraft that is in distress, only within set perimeters.

- 5 This could include taking the aircraft to a designated area; i.e., a landing site that is less populated. Reference: Actual Crash Document # 21, 22, 23, 47

[0150][0149] 10) AN INDIVIDUAL IS ALLOWED INTO THE FLIGHT DECK (COCKPIT) AREA, FOR WHATEVER REASON. THIS PERSON IS A HIJACKER OR TERRORIST AND THREATENS THE CAPTAIN The Captain or
10 employees in the flight deck (cockpit) will be able to set off a silent alarm. This device would start the Monitoring Device System (MDS) 30 and activate the Auto Controlling and Piloting System (ACPS) 40. The proper authorities will already be apprised of the situation, as it unfolds, (not after the fact), due to the implementation of these systems sending pertinent information. Simultaneously,
15 when the silent alarm is set off lights will turn on in the fuselage, notifying all flight attendants of a possible situation.

[0151][0150] At any time, the airline company/FAA/FBI or other designated authorities, in a united organized manner might consider it imperative to utilize any portion of the Security Aircraft Flight Equipment (SAFE) System-10
20 systems. The power is given to them to engage the Auto Controlling and Piloting System (ACPS) 40. This is done by the use of three parties, individual codes. The Secondary Aircraft Controller System (SACS) 60, is also implemented with three party, individual codes. More is discussed about the Secondary Aircraft Controller System (SACS) 60 later-on. The Anti-Crash ~~Systems~~ System (ACS) 20 is always
25 in operation; this portion of the Security Aircraft Flight Equipment (SAFE) 10 ~~system~~ systems cannot be overridden by anyone. Reference: Actual Crash Document # 22, 47

[0152][0151] 11) THE CAPTAIN IS DEAD AND TERRORIST(S) FORCES THE COPILOT IN POSITION TO PILOT THE AIRCRAFT It is important

to get the proper authorities involved as soon as possible by using a silent alarm device. This again allows an airline company, FAA and/or other groups to be aware of the terror occurring on the aircraft. The Monitoring Device System (MDS) 30 keeps them informed to the extent of how far the terrorist(s) have gone; it is done by sending both video and audio data. This data enables the authorities on the ground to take proper and necessary action to get control of the situation. This will commission them to exercise other portions of the Security Aircraft Flight Equipment (SAFE) 10 systems, such as Auto Controlling and Piloting System (ACPS) 40 even if the flight deck (cockpit) alarm device has been activated. It would be up to the proper authorities to elect this action if desired. Their options include ~~not only~~ utilizing the Auto Controlling and Piloting System (ACPS) 40, and ~~also, the~~ Secondary Aircraft Controller System (SACS) 60. This portion of the Security Aircraft Flight Equipment (SAFE) 10 systems is mentioned in scenario number eleven. I would like to emphasize that the Anti-Crash ~~Systems-System~~ (ACS) 20 is always operating to hold the aircraft on a plotted flight plan.

[0153][0152] Note: {Within the Anti-Crash ~~Systems-System~~ (ACS) 20 perimeters, as an aircraft reaches the perimeter edge, the system itself initiates and locks in the Auto Controlling and Piloting System (ACPS) 40. By the two of these systems working hand and hand together, it will not allow a terrorist to deviate from the plotted flight plan. When approaching a designated landing field, the aircraft will merely go into a holding pattern.

[0154][0153] Note: In this instance, authorities opted not to take control of an aircraft, during the plotted flight. For some reason they had, decided to wait until the aircraft's Anti-Crash ~~Systems-System~~ (ACS) 20 brought the aircraft to its destination. ~~At reaching~~ Reaching the destination the aircraft has gone into a holding pattern; at this time, authorities have determined to implement the Secondary Aircraft Controller System (SACS) 60. To do this, it is necessary the three party ~~securities code was necessary~~ parties security codes be utilized by the

separate corp. entities, allowing ~~for the remote~~ piloting to take possession and to safely land the aircraft or redirect to a different landing strip.

[0155][0154] 12) ALL PILOTS ARE DEAD DUE TO ANY REASON

Without a Pilot the aircraft will deviate from its set course and when this occurs, the
5 ~~Anti-Crash Systems~~ System (ACS) 20 automatically engages the Monitoring
Device System (MDS) 30 and the Auto Controlling and Piloting System (ACPS) 40.
This system brings the aircraft back onto the formatted course, which allows the
ground authorities to implement the Secondary Aircraft Controller System (SACS)
60. This is done with high security, multiple individual codes, operating from
10 several independent locations. The reason for the high-security initiation of these
codes is to regain control of the aircraft, allowing operation of remote piloting. In
order for the Secondary Aircraft Controller System (SACS) 60 to work, a security
aircraft must be within visual distance to take control of the aircraft. This allows
them to land the aircraft in a safe controlled environment or to continue on to the
15 designated flight plan. Reference: Actual Crash Document # 49

[0156][0155] 13) AN INDIVIDUAL TRIES TO TAKE THE AIRCRAFT

OFF COURSE The aircraft has a plotted course; this means the setting of the
perimeters for the longitude, latitude, and altitude are already set. When an aircraft
begins to leave this plotted flight plan, the ~~Anti-Crash Systems~~ System (ACS) 20
20 will simultaneously engage the Monitoring Device ~~apparatus~~ System (MDS) 30 and
the Auto Controlling and Piloting System (ACPS) 40. At this time, the Monitoring
Device System (MDS) 30 will notify the ~~airline company~~ Airline Company and also
other necessary entities. With the activation of the Auto Controlling and Piloting
System (ACPS) 40, the aircraft is brought back on course. It will hold this course
25 until it reaches ~~it's~~ its destination. At the end of the established course, the aircraft
goes into a holding pattern. This is buying time for the FAA and/or set departments
to employ the necessary actions to activate the Secondary Aircraft Controller
System (SACS) 60. This is begun by the input of a three party code from security
individuals, all from independent locations. Again, by use of these security codes,

the aircraft and passengers remain safe while control is allocated to the Secondary Aircraft Controller System (SACS) 60 to pilot by remote operation. The decision must then be made to continue on with the planned course or re-plot a new course. Reference: Actual Crash Document #8, 11, 13, 14, 15, 21, 38, 39, 47

5 [0157][0156] 14) WHAT STOPS A PILOT OR A TERRORIST FROM PLOTTING A NEW COURSE? The aircraft will not acknowledge any plot changes without approval. In order to change course three codes are needed from separate entities in various locations. If these codes are not entered the Auto Controlling and Piloting System (ACPS) 40 will not comply and process the changes. If there
10 is any tampering with or after three attempts of entry, the Auto Controlling and Piloting System (ACPS) 40 will immediately take over the piloting functions of the aircraft. It will hold the assigned course until it reaches the destination and then it will go into a holding flight pattern. The aircraft will remain in this pattern until the three party ~~code~~ codes are entered, or the Secondary Aircraft Controller System
15 (SACS) 60 is put into activation. Either of these being employed will then allow the aircraft to be retrieved. Reference: Actual Crash Document # 8, 9, 79

 [0158][0157] 15) A PERSON TRIES TO CRASH THE AIRCRAFT INTO THE GROUND WHILE AIRBORNE If any person(s) tries to crash the aircraft into the ground, the Anti-Crash ~~Systems~~ System (ACS) 20 will not allow the aircraft
20 to go below a set altitude. At that time, the Monitoring Device System (MDS) 30 and the Auto Controlling Piloting System (ACPS) 40 will automatically engage to take control of the aircraft. The Monitoring Device System (MDS) 30 will again send notification to the appropriate authorities, giving them time to assess the situation and make the proper decision for the safety of all individuals. The Auto
25 Controlling and Piloting System (ACPS) 40 that was employed simultaneously with the Monitoring Device System (MDS) 30 will bring the aircraft back onto the original flight plan. At this time if necessary, the FAA and/or other agencies can implement the Secondary Aircraft Controller System (SACS) 60, assigning remote piloting of the aircraft to a secondary craft, ~~this~~ This aircraft is being put in place at

close proximity. In order to disengage the Auto Controlling and Piloting System (ACPS) 40, it is necessary to use the high security multiple codes. This will allow FAA/Authorities, (if desired), to avert the aircraft to land in a more remote area. Reference: Actual Crash Document # 13, 14, 15, 38, 47, 60, 61, 80

5 [0159][0158] 16) A PERSON TRIES TO CRASH AN AIR PLANE INTO ANOTHER AIR PLANE Since the Anti-Crash ~~Systems~~ System (ACS) 20 is continuously active, it will identify ~~that there is another aircraft coming into its~~ it's airspace. At this time the Anti-Crash ~~Systems~~ System (ACS) 20 will activate the Auto Controlling and Piloting System (ACPS) 40 to elude the other aircraft that is
10 on a collision course. After the incident has passed, the Auto Controlling and Piloting System (ACPS) 40 will bring the aircraft back onto the assigned course. The Monitoring Device System (MDS) 30 is also activated concurrently with the Auto Controlling and Piloting System (ACPS) 40. The Monitoring Device System (MDS) 30 will transmit data of the aircraft's longitude, latitude and altitude (this is
15 for tracking purposes). This device is also transmitting video and audio data to the appropriate authorities on the ground. This transmission is an automatic response by the activation of the Monitoring Device System (MDS) 30. Reference: Actual Crash Document # 39, 50, 62, 63, 64

 [0160][0159] 17) SOMEONE TAMPERS WITH THE EXISTING
20 ONBOARD SYSTEM WHILE IN THE AIR (Not the SAFE System). The system is linked into the controller devices BEFORE they reach the control panel. (*The only part of the Security Aircraft Flight Equipment (SAFE) 10 systems that is accessible by a person while in flight is the keypad and thumb scan device, alarm devices and cameras.*) The control panel sends signals to the Security Aircraft Flight Equipment
25 (SAFE) 10 ~~system~~ systems, which reads the circuit loop. In the event that the wires are cut or tampered with at the control panel, the Security Aircraft Flight Equipment (SAFE) 10 ~~system~~ systems identifies a break in the circuit and it will immediately activate the Auto Controlling and Piloting System (ACPS) 40 and the Monitoring Device System (MDS) 30. The Auto Controlling and Piloting System (ACPS) 40

will put the craft on autopilot, and hold the set course. The Monitoring Device System (MDS) 30 allows the proper authorities to be apprised of the situation. This will notify them of which portion of the aircraft control system has been tampered with, or what has developed a malfunction. It is up to the authorities to decide what to do. They can give control back to the pilot if they wish, or to take control themselves through implementing the Secondary Aircraft Controller System (SACS) 60. Refer to the Secondary Aircraft Controller System (SACS) 60 information.

[0161][0160] NOTE: If desired a reader screen maybe installed within the flight deck (cockpit) area. This will receive the information identifying the equipment malfunction. With this screen, it allows the pilot to know where the problem has occurred and to possibly correct the problem. With the ground's personnel having full knowledge of the situation they can offer necessary assistance by walking a person through temporary repair of the component.

Reference: Actual Crash Document # 14, 38, 71

[0162][0161] 18) WHAT STOPS SOMEONE FROM ATTEMPTING TO SHUT DOWN THE ENGINES WHILE IN THE AIR? The existing system would have to be wired through the Security Aircraft Flight Equipment (SAFE) system 10, which would not allow any type of shut down while the aircraft RPM are above an idle. Upon any attempt of tampering, the Anti-Crash Systems-System (ACS) 20 will engage the Auto Controlling and Piloting System (ACPS) 40 and lock out any other efforts to shut down the aircraft. In the event case of an emergency while in flight, such as the need to shut down a motor, the Security Aircraft Flight Equipment (SAFE) 10 system-systems would already identify this emergency and make an allowance.

[0163][0162] Note: Identification is made through the existing safety equipment that is already operational on the aircraft or the Security Aircraft Flight Equipment (SAFE) system-10 systems can institute the necessary sensors if desired by aircraft purchaser.

[0164][0163]-19) WHAT HAPPENS IF THE PILOT GETS DISORIENTED? --(i.e. spatial disorientation). In this particular case, the pilot becomes disoriented for whatever reason. The aircraft deviates from the assigned course. The Anti-Crash ~~Systems~~ System (ACS) 20 identifies that there is a
5 problem, immediately ~~operating~~ directing signaling the Auto Controlling and Piloting System 40 (ACPS) 40 to maneuver the aircraft back to the appropriate course. At the same time the Monitoring Device System (MDS) 30 immediately participates and sends data to the appropriate authorities. Automatically, the authorities will have access to audio and video information, ~~plus the~~ The data will
10 include the aircraft location and vitals (such as longitude, latitude, altitude, engine conditions, fuel level, etc.) This will assist the authorities to make an educated determination as to what their options are. If the authorities deem it necessary, they can ~~make arrangements~~ arrange to engage in the Secondary Aircraft Controller System (SACS) 60. Once this system has been implemented, the
15 authorities may re-plot a course to safely bring the aircraft to a less populated airstrip. Reference: Actual Crash Document # 56, 70

[0165][0164]-20) THE PILOT IS LOST DUE TO STORM, ETC. (Bermuda triangle) The Security Aircraft Flight Equipment (SAFE) system 10 would record the path that the aircraft had traveled. The tracking system would hold all
20 essential information, such as altitude, longitude, latitude, airspeed, etc. This would allow for the airplane to back track to a location where the pilot would be able to identify and resume control of the aircraft. Reference: Actual Crash Document # 19

[0166][0165]-21) WHAT HAPPENS DURING SEVERE ATMOSPHERIC DISTURBANCES? If the turbulence becomes beyond human
25 capabilities to maneuver in, and the pilot is unable to keep the aircraft within the set perimeters, the Auto Controlling and Piloting System (ACPS) 40 will commence and bring the craft back on course. The pilot also has the option to engage the Auto Controlling and Piloting System (ACPS) 40 at any time.

[0167][0166] NOTE: If the proper sensors are put in place the system could also identify excessive vibrations in areas that in the past have caused airplane crashes (engine areas, wing, tail, stabilizers, etc.). Reference: Actual Crash Document # 19, 20

5 [0168][0167] 22) THE WEATHER IS SO SEVERE THE PILOT CANNOT MANEUVER THE AIRCRAFT Upon the aircraft leaving the programmed flight pattern, automatically the Monitoring Device System (MDS) 30 will automatically, alert the authorities on the ground that the aircraft or pilot maybe having difficulties. The information transmitted would be video and audio, as well
10 as, other data to determine the cause of why the aircraft is having problems staying within the designated pattern. ~~The~~ Within the data sent is also the location of the aircraft, and the identification of the aircraft registration. Simultaneously, the Monitoring Device System (MDS) 30 and the Auto Controlling and Piloting System (ACPS) 40 are activated by the Anti-Crash ~~Systems~~ System (ACS) 20. This
15 system will enhance the maneuverability of the aircraft beyond human capability ~~of the aircraft~~, ~~this is~~ due to the computer having quicker reaction time to changes in conditions surrounding the aircraft. This eradicates the documented 95% of human error involving airplane crashes. The Auto Controlling and Piloting System (ACPS) 40 already has a pre-plotted course to fine tune the direction of the aircraft,
20 keeping this plane on this course. These systems continue monitoring, adjusting course, and notifying ground control individuals. Once the aircraft is out of the severe weather situation, the company's pilot can activate his personal code and thumb scan to resume piloting the aircraft again. Reference: Actual Crash Document # 10, 18, 45, 70, 72

25 [0169][0168] 23) A HIJACKER TRIES TO CRASH AN AIRPLANE BY RUNNING IT OUT OF FUEL The Anti-Crash ~~Systems~~ System (ACS) 20 will analyze the functions of the aircraft. If any of the control panel devices get outside of the minimum standards set by the manufacturer, the Monitoring Device System (MDS) 30 will alert pilots and also automatically notify authorities and/or individuals

in charge. This will allow the ground authorities to identify a potential situation such as low fuel levels, low fuel line pressures, low oil pressures, or any abnormalities of existing onboard systems. With the connection between the Anti-Crash Systems System (ACS) 20 and the Monitoring Device System (MDS) 30 both pilot(s) and
5 authorities can make all the calculations necessary to determine the best action necessary for the safety of the passengers and crew members. They might determine to bring the aircraft to a closer airfield. They also have the choice of using the Secondary Aircraft Controller System (SACS) 60 by entering the multiple-code process. This portion of the system gives them control of the aircraft.
10 For the Anti-Crash Systems System (ACS) 20 to function the operators would still be required to initiate an alternative course with a final destination. (They would no longer be depending on any pilot in the distressed aircraft-). Reference: Actual Crash Document # 22, 43, 45

[0170][0169] 24) WHAT ABOUT IN-AIR REFUELING? CAN IT BE
15 DONE WITH THE ANTI-CRASH SYSTEMS (ACS)? In the case of refueling, we are setting up a safety device so that two things occur: 1) the two Anti-Crash Systems (ACS) 20 would link. These systems will make the adjustments and corrections to hold the aircraft parallel and equal with the in-flight fuel tanker 2: The 2) the aircraft would be brought into a designated safe distance for refueling.
20 Reference: Actual Crash Document # 59

[0171][0170] 25) ANOTHER AIRCRAFT DOES NOT HAVE THE ANTI-CRASH SYSTEM (ACS) 20 ONBOARD AND TRIES TO INTRUDE INTO THE SAME AIRSPACE (note: plane to plane) The Anti-Crash Systems (ACS) 20 identifies another aircraft through the radar controller. The system will implement
25 the Monitoring Device System (MDS) 30, this 30. This device sends a signal to the aircraft asking for identification. It also sends data giving the approximate location of the other craft to authorities on the ground. If this other aircraft becomes too close the Anti-Crash Systems System (ACS) 20 will maneuver away from the pushing

aircraft, however, it will return to its designated course through the Auto Controlling and Piloting System (ACPS) 40.

~~[0172][0171]~~ 26) WHAT IF AN AIRCRAFT DOES NOT IDENTIFY ITSELF? The Security Aircraft Flight Equipment (SAFE) 10 ~~system~~systems,

5 through the Monitoring Device System (MDS) 30, sends data notifying the proper authorities of an unidentified aircraft in the area. Reference: Actual Crash Document # 7

~~[0173][0172]~~ 27) WHAT KEEPS ANOTHER AIRCRAFT FROM FORCING THE AIRCRAFT TO AN UNWANTED AREA? (After it is on-Autopilot

10 autopilot) In detection of another aircraft in the set airspace, the Monitoring Device System (MDS) 30 notifies the authorities by sending data. Information is coming in from the (radar, GPS, and tracking mechanisms, etc.) ~~to~~into the Anti-Crash ~~Systems-System~~ (ACS) 20, ~~it~~It will then take all this information and activate the Auto Controlling and Piloting System (ACPS) 40. This system will work in eluding
15 any efforts in manipulating the aircraft off the assigned course. It will always rebound back to its pre-designated course.

~~[0174][0173]~~ 28) WHAT STOPS AN AIRCRAFT FROM GETTING INTO ANOTHER AIRCRAFT'S ~~JET-STREAM~~ JET STREAM (Wake Turbulence)?

The Security Aircraft Flight Equipment (SAFE) 10 ~~system~~systems will not allow
20 this to happen. Using the Anti-Crash ~~Systems-System~~ (ACS) 20 and Auto Controlling and Piloting System (ACPS) 40 perimeters of airspace are set up per aircraft. These perimeters are pre-determined for flight safety. Each aircraft upon entering this designated airspace would deviate away from each other, not allowing ~~for~~ either aircraft to become too close, disrupting the airflow beyond a
25 reasonable tolerance. Reference: Actual Crash Document # 1, 85

~~[0175][0174]~~ 29) WHAT IF THE AIRCRAFT NEEDS TO BE REROUTED TO ANOTHER AIRPORT? In this instance, the pilot would need to get confirmation to re-plot to an alternative destination. Upon the new course being correct and acceptable, contact with the authorities on the ground would have to

implement the multiple-code process to finalize the adjusted course. Again, ~~this is~~
~~these are the three party code-codes~~ from three separate locations, to heighten
air-flight security in the event of a terrorist threat. Reference: Actual Crash
Document # 52

5 ~~[0176][0175]~~ 30) IN CASE OF AN EMERGENCY THE AIR PLANE
NEEDS TO RETURN TO THE AIRPORT Not a problem as long as the plane stays
within the perimeters plotted according to a return plan.

~~[0177][0176]~~ 31) A COMMERCIAL FLIGHT PLOTS A COURSE
OVER FOREIGN AIRSPACE The Security Aircraft Flight Equipment (SAFE)
10 ~~system~~ 10 systems on the plane will simultaneously alert and identify its
registration to proper authorities in both countries. This will allow both countries to
have the important information for diplomatic affairs if necessary in solving the
airspace situation peacefully. Reference: Actual Crash Document # 7, 75, 83

~~[0178][0177]~~ 32) AN INDIVIDUAL OR GROUP OF INDIVIDUALS
15 BECOMES A THREAT IN THE FUSELAGE AREAS A member of the crew has the
accessibility to the silent alarm devices which are installed in several areas
throughout the aircraft. These alarm devices will notify other members of the crew,
including members in the flight deck (cockpit) area, alerting them of a potential
problem occurring on the aircraft. At the same time, the alarm device initiates the
20 Monitoring Device System (MDS) 30. Now that the appropriate authorities are
aware, they can view and analyze the events that are taking place on the aircraft.
This will enable them to determine the necessary actions to employ. Their choice
might be to contact the Captain, ~~giving him coded authority to change course if~~
~~necessary, or, for them to implement other sections of the combined system. with~~
25 the decision to implement the Security Aircraft Flight Equipment (SAFE) 10
systems three-code process. Reference: Actual Crash Document #4, 16, 21

~~[0179][0178]~~ 33) WE THINK NO ONE IS ALIVE ON THE AIRCRAFT;
WE NEED TO BRING IT DOWN_Let's say a possible terrorist sets liquid or gas
toxins in the airways of the aircraft; this has immobilized individuals. The Anti-

Crash ~~Systems-System~~ (ACS) 20 would go in effect when the airplane is not being held into its flight perimeters. It would activate the Auto Controlling and Piloting System (ACPS) 40 to take over the controls; it will bring the aircraft back on course and hold the charted course. The Monitoring Device System (MDS) 30 is also
5 implemented at the same time. It sends video data from the flight deck (cockpit) area, informing the authorities no one is awake or has their faculties in order to fly the aircraft. These videos also are of the walkways in the fuselage area, allowing the authorities to be totally aware of the situation. The audio data sent has not detected any sound in this case. With the Monitoring Device System (MDS) 30
10 operating it gives the authorities on the ground necessary data to determine what course they need to take. They have the option of applying the Secondary Aircraft Controller System (SACS) 60. This allows them to retrieve the aircraft and bring it into an airfield. If necessary, they can divert it to a secured location.

[0180][0179] 34) WHAT ABOUT THE POSSIBILITY OF HACKING
15 OR DEFLECTION DURING REMOTE PILOTING, WHEN THE SECONDARY AIRCRAFT CONTROLLER SYSTEM (SACS) 60 IS IN EFFECT The secondary aircraft that will be controlling the first aircraft has to be within a specified distance from the first aircraft. The two controllers of the systems must make a connection by using the codes and the security key. If they opt to make a course correction it
20 must be accepted and verified by secured authorities.

[0181][0180] Note: The Security Aircraft Flight Equipment (SAFE) 10 ~~system-systems~~ allows for the use of a single party code for total override of the aircraft (remember now, the Anti-Crash System (ACS) 20 portion of the Security Aircraft Flight Equipment (SAFE) ~~system-systems~~ CANNOT be disabled). This
25 code would come from the National Security Department (such as a presidential override). This single party code would be utilized in the event that there is a failure in activation of the other codes due to a hijacking.

[0182][0181] A Single party code for total override of the aircraft for Secondary Aircraft control in the event the other codes are being deflected or not activating them because of a hijacker.

- [0183][0182] This code would come from the National Security
5 Department, such as a presidential override. This override code must be implemented from a secondary aircraft that is set at a designated distance.

[0184][0183] 35) THERE IS AN ELECTRICAL POWER OUTAGE
ONBOARD THE AIRCRAFT (Not applicable upon an engine failure) In the event of an electrical power outage, the Security Aircraft Flight Equipment (SAFE) 10
10 ~~system~~ systems would not be effected since it would be wired through a separate breaker panel. The equipment is connected to the existing systems of the aircraft, so that it receives data from all of its components.

[0185][0184] When a circuit loop is broken, it cannot repair anything. It will, through the Monitor Device System (MDS) 30, send data to the ground
15 telling them of a problem, providing critical flight information (i.e., longitude, latitude, etc.). The ground control can then "talk the pilot through", or allow them the option to use other parts of the system (Auto Controlling and Piloting System (ACPS) 40, or Secondary Aircraft Controller System (SACS) 60. Any questions on what these systems are, please refer to Security Aircraft Flight Equipment System
20 (SAFE) 10 systems document information Reference: Actual Crash Document # 57, 58

[0186][0185] 36) WHAT IF THE AIRCRAFT'S (SAFE) SYSTEM MALFUNCTIONS? In any given system, there lies the possibility of malfunction. Malfunction of the Security Aircraft Flight Equipment (SAFE) ~~system~~ 10 systems
25 does not affect the operation of the existing systems on the aircraft. With the equipment's design on any aircraft, it operates independently from the aircraft system. To limit the loss of security due to any given malfunction, the system uses independently powered hardware. There is an equipment option to install a secondary-second Security Aircraft Flight Equipment (SAFE) system 10 systems in

any given aircraft (see document information, subheading: Backup System). The Security Aircraft Flight Equipment (SAFE) ~~system-10~~ systems is linked with the existing system to receive data in order to perform it's own duties. The Monitoring Device System (MDS) 30 and Anti-Crash ~~Systems-System~~ (ACS) 20 are designed
5 to notify proper authorities of any problem in any sectors. This again does not affect other portions of the Security Aircraft Flight Equipment (SAFE) ~~10-system~~ systems, because its units are independently connected to the system.

[0187][0186] The aircraft's existing computers use various programs in informing topographically where their location is in conjunction with the ground.
10 Using these, the Security Aircraft Flight Equipment (SAFE) ~~10 system-compares~~ systems compare coordinates with the data from the plotting equipment before take-off. If a plotted course is going to cause a collision, an alarm will sound and a light will flash on the control panel indicating that this is an inappropriate course. The pilot will have to make the corrections in order for the aircraft engine and/or in
15 some cases the turbines to power up.

[0188][0187] 37) WHAT HAPPENS IF AIRCRAFT LOSES AIR PRESSURE? The Security Aircraft Flight Equipment (SAFE) ~~10 system-systems~~ would engage the Monitoring Device System (MDS) 30 ~~which-that~~ would be receiving data from the sensors of the aircraft. It will notify the pilot of a problem,
20 as well as enlighten the proper authorities on the ground. Reference: Actual Crash Document # 17, 77

[0189][0188] 38) WHAT IF THE PILOT IS A TERRORIST? During takeoff and flight, NO pilot can take the plane outside of the perimeters of a plotted course. The course can only be changed upon from the proper authorities on the
25 ground. At this time then other security portions of the system would need to be implemented. Reference: Actual Crash Document # 8, 9, 38, 39

[0190][0189] 39) A PERSON TRIES TO CRASH THE AIRPLANE INTO A BUILDING, BRIDGE OR OTHER OBJECT. Using this scenario because of what occurred on Sep. 11, 2001. The ~~Structure-structure~~ Anti-Crash Systems

System (ACS) 20 such as the Building Anti-Crash System 220, would be used. This system has two separate groups of fixed perimeters encompassing the structure; 1) ~~set~~ Set of perimeters marks an area for the program to send a warning signal to the pilot, letting him know that he is approaching into a no fly zone area, and 2) ~~set~~ Set of perimeters marks an area for the program to send a signal to the aircraft's Anti-Crash ~~Systems~~ System (ACS) 20. Upon receiving, ~~that the signal~~ the aircraft's Anti-Crash ~~Systems~~ System (ACS) 20 will immediately initiate the Auto Controlling and Piloting System (ACPS) 40. In the event that the pilot or terrorist elect to ignore the warning and enter into the no fly zone area, the Auto Controlling and Piloting System (ACPS) 40 averts the aircraft outside of the protected air zone and brings it back on course. In order for an individual to take over the controls after the Auto Controlling and Piloting System (ACPS) 40 has ~~that have~~ been activated, there is a three-stage process to be completed. This three-stage process is 1) a commissioned pilot must enter his personal code, and thumb print. 2) ~~he~~ He must receive another code for entry; this is from the airline company security or designated authorities, and 3) ~~there~~ There would yet be another security code that would need to be entered to give him control of the aircraft (could be from the offices of the FAA, FBI, or Airline security). In the event that the pilot does not receive or does not enter the last two codes, then the aircraft will continue on the plotted assigned course. At the end of the flight plan, it will continue in a holding pattern until someone takes over the aircraft. This can be done either by entering the codes needed or by employing the Secondary Aircraft Controller System (SACS) 60. ~~The last system is also secured~~ Multiple individuals also secure the last system through multiple codes ~~by multiple individuals~~. By implementing the Secondary Aircraft Controller System (SACS) 60, it relinquishes the restrained aircraft to be piloted by remote control. This will allow landing of the aircraft at its designated airfield or divert it to a secured location. The Monitoring Device System (MDS) 30 simultaneously will participate by informing all appropriate authorities. It will send vital information that allows them to make an

educated and precise decision in this event. This essential information is through video, audio and additional data that identifies the aircraft. This contains the position of an aircraft, as well as the status of the fuel levels, fuel line pressures, R.P.M., onboard controls, etc.

5 ~~[0191][0190]~~ Note: Another object of the system is to allow proper authorities (such as, Police Dept., Fire Dept., local authorities) notice BEFORE an attempted disaster strikes. It ~~basically will~~ not allow the aircraft to hit a building, bridge or object, providing the structure has the Anti-Crash ~~Systems-System~~ (ACS) on it. This can also be linked into an alarm system so that an evacuation process
10 can be implemented; this is allocating precious moments in the event that there could be a possibility of other types of an attack.

~~[0192][0191]~~ LET'S CHANGE THE HISTORY OF ~~SEP. 11~~
SEPTEMBER 11, 2001 BY USING THE SECURITY AIRCRAFT FLIGHT
EQUIPMENT (SAFE)-~~system~~ 10 SYSTEMS. This example was taken from the
15 ~~Sep. September. 11, 2001~~ event. On this day the aircraft that struck the twin towers did not have any form of Anti-Crash ~~Device-System~~ (ACDS) (ACS) 20
onboard, neither did the twin towers have any form of an alarm or anti warning device installed-~~(ACDS)~~ Anti-Crash System (ACS) 20. Now lets change the 2001
event. Before the crash there was a system installed on the building, the
20 developed Security Aircraft Flight Equipment (SAFE) ~~10-system~~ systems. This is an Anti-Crash System (ACS) 20 and early warning device; it warns of an aircraft approaching the building's airspace. As the alarms sound of an air raid, this gives the occupants precious moments for evacuation (this is BEFORE the building is struck). As soon as the aircraft reaches the no fly zone area of the building, data is
25 sent to authorities (fire departments, police departments and necessary officials) giving pertinent information.

~~[0193][0192]~~ Let's add the Anti-Crash ~~Systems-System~~ (ACS) 20 to the aircraft as well. The warning devices in the building emit signals that broadcast distance and height perimeters to the aircraft Anti-Crash System (ACS) 20. With

this information to the Anti-Crash System (ACS) 20 it will engage the Auto Controlling and Piloting System (ACPS) 40 portion of the Security Aircraft Flight Equipment (SAFE) ~~system~~ 10 systems to divert the aircraft from the twin towers airspace. Locking out the pilot's control of the aircraft, it will not allow the pilot to
5 regain control for a suicide terrorist attack. The Monitoring Device System (MDS) 30 would simultaneously activate and notify the necessary authorities (FAA/FBI). This notification is audio and video data from inside the aircraft and ~~also~~ vital information about the aircraft (location, registration, etc.). Since the pilot is a terrorist, it is important for the authorities to take control of the aircraft. Approval is
10 given by entering a three party security code from independent locations, allowing control by remote access from a secured secondary aircraft. By implementing this system, authorized individuals will be able to chart a new course if desired.

[0194][0193] Note: See the Secondary Aircraft Controller System (SACS) 60 portion under the Security Aircraft Flight Equipment (SAFE) 10 systems
15 document information. Reference: Actual Crash Document # 8, 9, 79

[0195][0194] 40) SOMEONE TAMPERS WITH A BUILDING OR OTHER STRUCTURE'S SAFETY SYSTEM EQUIPMENT The system is connected to a silent alarm unit, alerting authorities of the attempted efforts in tampering with the Buildings Anti-Crash ~~Systems~~ System (ACSBACS) 20 220. The
20 Building Anti-Crash System (ACSBACS) 20 220 apparatus is connected to its own Monitoring Device System (MDS) 30; this device will send video and audio data to the police in identifying the perpetrators.

[0196][0195] As the police respond to the incident, the Safety Aircraft Flight Equipment's Equipment (SAFE) 10 systems technical technician-department
25 will also be contacted to correct any damages that may have occurred to the system.

[0197][0196] Note: See the Monitoring Device System (MDS) 30 on structures portion under the Safety Aircraft Flight Equipment (SAFE) 10 systems document information.

[0198][0197] 41) THERE IS A POWER OUTAGE IN A BUILDING OR
ON A BRIDGE, DUE TO ANY REASON INCLUDING SABOTAGE The system
remains fully operational in a power outage situation. It will be connected to the
existing emergency power source. In the event that the building lacks an
5 emergency power source, the Security Aircraft Flight Equipment (SAFE) System
10 systems would be supplied with an emergency power backup. ~~This~~ These
Security Aircraft Flight Equipment (SAFE) System ~~10 systems~~ would be isolated in
a secure location within the structure.

[0199][0198] 42) WHAT IF THE STRUCTURE SECURITY
10 AIRCRAFT FLIGHT EQUIPMENT (SAFE) SYSTEM MALFUNCTIONS? In any
given system there lies the possibility of malfunction. Each unit of the Security
Aircraft Flight Equipment (SAFE) System ~~10 systems~~ is independently wired to the
building or structure. These two portions of the system: the Anti-Crash System
(ACS) 20 and ~~Monitoring~~ monitoring Device (MDS) 30 apparatus are connected
15 through a complex marriage. Each of these units has a backup support system.
Upon one of the portions malfunctioning, the backup system would activate still
giving protection, also, notifying the building authorities and authorized service
technicians of the malfunction.

[0200][0199] Note: This will not affect any of the assisting alarms that
20 are wired into the structure for security or fire systems.

[0201][0200] 43) WHAT IF SOMEONE DOES SUCCEED IN
REMOVING ANY PART OF THE SECURITY AIRCRAFT FLIGHT EQUIPMENT
(SAFE) ~~SYSTEM~~ 10 systems? On the ground, the system shuts down the aircraft,
disabling it, just like if you take the computer from an automobile. The ~~aircraft will~~
25 ~~need all facets of the computer to be active and functional to operate.~~ automobile
would no longer operate, same with the aircraft could no longer fire up. All the
facets of The Anti Crash System (ACS) 20 need to be in place and active, in order
for the aircraft to be back in service.

[0202][0201] In the air, all sectors of the Security Aircraft Flight Equipment (SAFE) 10 Anti Crash System (ACS) 20 computer components are not accessible. But to answer in the case that they ripped the aircraft apart in the air, the disabling of the Security Aircraft Flight Equipment (SAFE) System 10 just
5 would not affect the aircraft function to fly the aircraft manually.

[0203][0202] Again in any of these instances the Monitoring Device System (MDS) 30 would give attention to the proper authorities.

[0204][0203] 44) THE MONITORING DEVICES ARE TAMPERED WITH The Monitoring Devices Device System (MDS) 30 are is linked to the brain
10 of the operation, the Anti-Crash Systems-System (ACS) 20 which is the brain of the operation. When any part of the system (devices, wiring, camera's or sensors) is altered or the power changes, the Anti-Crash Systems-System (ACS) 20 engages the Monitoring Device System (MDS) 30 and contacts the authorities. The police and the security department will be notified through the silent alarm
15 unit. In the Security Aircraft Flight Equipment (SAFE) System-10 systems, all of the external components are individually connected through a complex marriage. When one is disrupted, it does not affect the performance of the other portions of the Security Aircraft Flight Equipment (SAFE) System 10.

[0205][0204] The FAA would be immediately contacted through the
20 Monitoring Device System (MDS) 30 with video and data from the Security Aircraft Flight Equipment (SAFE) 10 computer-system systems. This would not affect the functionality of the other cameras or alarm buttons since they are individually wired.

[0206][0205] 45) SOMEONE DAMAGES OR DISABLES THE
25 KEYPAD AND/OR THUMB SCAN UNIT In the event that these input devices are damaged the Security Aircraft Flight Equipment (SAFE) 10 system-systems automatically takes over. All the portions of this system start simultaneously. The Monitoring-monitoring Device (MDS) 30 portion notifies ground personnel and/or authorities that tampering or damage to the aircraft has developed. Through this

data they will be able to determine where the problem has occurred. Utilizing the video and monitoring (MDS) portion of this system they will be able to see who is in control on the aircraft. The Auto Controlling and Piloting System (ACPS) 40 have also been implemented at this same time, so the aircraft is being kept on the designated course. This is allowing the authorities to put in action the Secondary Aircraft Controller System (SACS) 60 if necessary, or relinquish the controls of the aircraft to the Captain through a three party code process.

[0207][0206] 46) WHAT IF THE HIJACKER BREACHES SECURITY AND ACCESSES THE CODES?_The Anti-Crash System (ACS) 20 portion of the system ~~will never be unlocked~~ Security Aircraft Flight Equipment (SAFE) 10, can not be coded out to shut down. The Hijacker cannot take the aircraft on a course endangering the passengers. The hijacker also would not be able to stop the implementation of the Secondary Aircraft Controller System (SACS) 60. The authorities on the ground have the option to engage the Monitoring Device System (MDS) 30 "at will", collecting information from the aircraft (identification, location, etc.) as well as audio and video data from within the flight deck (cockpit) and fuselage.

[0208][0207] Note: Administrative rights can be assigned in many different combinations, allowing for limited access in designated programs within the Security Aircraft Flight Equipment (SAFE) system-10 systems

[0209][0208] 47) WHAT ABOUT CODES BEING HACKED? This system is designed with checks and balances. We have put in for security reasons a three party code arrangement and using three totally separate locations, as well as, different facets of the industry such as airline companies, FAA, FBI, etc. These codes use not only numbers but also letters and characters as well using an encrypted key on all systems. For the use of identity, the key is on a short-term registration license. With the application of these encrypted key codes listed above, ~~it also requires a live thumbprint~~ is also required.

[0210][0209] NOTE: Sensed body temperature or pulse scan.

[0211][0210] 48) WHAT ABOUT COMPUTER HACKING? The Security Aircraft Flight Equipment (SAFE) system-10 systems is protected by using a concealed dongle key, as well as, an encrypted pilot dongle or chip key that is used in connection with the thumb scan. Without the operation of both of these, the system will not allow the aircraft to fly.

[0212][0211] NOTE: The concealed dongle is the Security Aircraft Flight Equipment (SAFE) System-10 systems license key. The other dongle key is the pilot's personal key, also licensed. Even in the event of a lost or stolen pilot's key, the Security Aircraft Flight Equipment (SAFE) System-10 systems will not identify an improper user or pilot.

[0213][0212] ~~Concealed~~ The concealed dongle license key is located in a different location on the aircraft or structure and possible thumb scan programmed within this key chip.

[0214][0213] ~~Proprietary~~ A proprietary master dongle key is for service technicians only. This will only allow them to service the equipment; it will not allow them licensed rights to operate the aircraft.

[0215][0214] 49) WHAT ABOUT MAGNETIC DISTURBANCES? The solid-state equipment, I.E., ROMS and PROMS, etc. chips are not affected by magnets.

20 [0216][0215] ACTUAL CRASH DOCUMENT

[0217][0216] 1. Date: May 30, 1972 Location: Dallas/Ft. Worth, Tex. Texas Airline: Delta Air Lines Aircraft: Douglas DC-9-14 Registration: N3305L Fatalities/No. Aboard: 4:4 Details: While practicing touch and go landing the aircraft crashed after getting caught in the wake turbulence of a DC-10.

25 [0218][0217] 2. Date: Feb. 16, 1998 Location: Taipei, Taiwan Airline: ~~China Airlines~~ Aircraft: ~~Airbus A300-600R~~ Registration: ~~B-1814~~ Fatalities/No. Aboard: ~~196:196~~ +7 Details: The aircraft was attempting to land at Taipei's international airport in rain and fog when the crew requested a go-around. The plane crashed into a residential neighborhood, ripping the roofs off several

structures, skidding into a rice paddy and bursting in flames. DFDR data showed complete autopilot disengagement just after landing clearance. This was followed by an attempted manually flown go-around with falling airspeed and a pitch-up of 40 degrees followed by a gain of 1,000 feet in altitude, total stall and a dive resulting in impact with the ground.

[0219][0218] 3. Date: Sep. ~~Sept.~~ 26, 1997 Location: Buah Nubar, Indonesia Airline: Garuda Indonesia Airlines Aircraft: Airbus A300-200 B4 Registration: PK-GAI Fatalities/No. Aboard: 234:234 234: Details: The aircraft crashed into mountainous terrain 15 minutes before it was due to land at Medan on a flight from Jakarta. The aircraft crashed 20 miles from the airport. ATC error in directing the plane in the wrong direction into mountainous terrain that was obscured by smoke and haze due to forest fires in the area.

[0220][0219] 4. Dec. 26, 1994 Location: Algiers Airport, Algeria Airline: Air France Aircraft: Airbus A300-1C B2 Registration: F-GBEC Fatalities/No. Aboard: 7:170 Details: The aircraft was hijacked by terrorists. Seven passengers were killed when the plane was stormed. Hijackers killed 3 passengers.

[0221][0220] 5. Apr. 26, 1994 Location: Komaki, Aichi, Japan Airline: China Airlines Aircraft: Airbus A300-600R Registration: B-1816 Fatalities/No. Aboard: 264:271 Details: While on ILS approach to Nagoya Airport, at an altitude of 1,000 feet, the first officer inadvertently triggered the TOGA (take-off go-around) lever. The crew tried to override this situation by turning off the auto throttle and reducing air speed. The aircraft stalled, hit the runway tail first and burst into flames. The plane crashed because of an extreme out of trim configuration brought about by the fact that the tail plane setting had moved automatically and undetected to a maximum nose up position. The plane climbed at a steep angle until it stalled. The crew could have saved the aircraft even in the final seconds had they reverted to basic flight procedures and switched off the autopilot

[0222][0221] 6. Date: Sep. 28, 1992 Location: Kathmandu, Nepal Airline: Pakistan International Airlines Aircraft: Airbus A300-200 B4 Registration:

~~AP BCP Fatalities/No. Aboard: 167:167 Details: The plane hit cloud covered high ground while attempting to land 9 miles short of the runway. The pilot began the descent too early and had miscalculated the aircraft's altitude. Failure of the crew to follow prescribed procedures.~~

5 ~~[0223][0222] 7. Date: Jul. 3, 1988 Location: Persian Gulf Airline: Iran Air Aircraft: Airbus A300-200 B2 Registration: EP-IBU Fatalities/No. Aboard: 290:290 Details: Shot down by the U.S. Navy vessel U.S.S. Vincennes with a surface-to-air missile. The Vincennes was protecting other U.S. ships in the area during hostilities. A misread radar indicating the plane was descending and the fact~~
10 ~~that the aircraft did not respond to challenges led to the firing of the missiles.~~

~~[0224][0223] 8. Date: Sep. 11, 2001 Location: New York City, N.Y. New York Airline: American Airlines Aircraft: Boeing 767-200ER Registration: N334AA Fatalities/No. Aboard: 92:92+1000s? Details: The aircraft was hijacked shortly after it left Logan International Airport in Boston and crashed into the north~~
15 ~~tower of the World Trade Center. The building subsequently collapsed. It was one of four planes hijacked by terrorists.~~

~~[0225][0224] 9. Date: Sep. 11, 2001 Location: Pentagon City, Va. Virginia (Washington D.C. DC Metro Area) Airline: American Airlines Aircraft: Boeing 757-200 Registration: N644AA Fatalities/No. Aboard: 64:64+100s? Details:~~
20 ~~Shortly after taking off from Dulles International Airport, the aircraft was hijacked and flown into the side of the Pentagon building. It was one of four planes hijacked by terrorists.~~

~~[0226][0225] 10. Date: Jun. 1, 1999 Location: Little Rock, Ark. Arkansas Airline: American Airlines Aircraft: McDonnell Douglas Super MD-80 (MD-82) Registration: N215AA Fatalities/No. Aboard: 11:145 Details: The plane~~
25 ~~was on a flight from Dallas/Fort Worth, Tex. Texas to Little Rock, Ark. Arkansas. While attempting to land at Little Rock Airport, the flight encountered heavy thunderstorms, rain and strong winds. The aircraft landed fast and hard, skidded~~

~~off the end of the runway and struck a landing light tower, breaking into three parts and bursting into flames.~~

~~[0227][0226] 11. Date: Dec. 20, 12, 1995 Location: Buga, Valle del Cauca, Colombia Airline: American Airlines Aircraft: Boeing 757-200 Registration: N651A Fatalities/No. Aboard: 160:164 Details: While on a flight from Miami, Fla. FL to Cali, Columbia the aircraft crashed into mountainous terrain 38 miles north of Cali while attempting to land. On approach, the crew were requested to report over Tulua VOR which they already passed. This confused them and they decided to go direct to Roze beacon. Entering the abbreviation "R", incorrectly steered the plane towards Bogota. More than a minute into the turn the crew steered manually toward Cali, but this now took them into the path of a mountain. Crew error. Lack of situational awareness, failure to adequately plan and execute the approach, failure to realize that the FMS had turned the aircraft toward mountains. Crew also neglected to retract the speed brakes after the ground proximity warning system alert. Lack of adequate radar. Different Flight Management System naming convention from that published in navigational charts.~~

~~[0228][0227] 12. Airline: Simmons Airlines (American Airlines/American Eagle) Aircraft: Aerospatial ATR-72-200 Registration: N401AM Fatalities/No. Aboard: 68:68 Details: The aircraft was in a holding pattern and was descending to a newly assigned altitude of 8,000 feet when it experienced an uncommanded roll and excursion and crashed during a rapid descent. Icing. The design of the rubber de-icing boot was insufficient to deal with icing on the wings. ATR's failed to completely disclose to operators and incorporate in the ATR-72 airplane flight manual, flightcrew operating manual and flightcrew training programs, adequate information concerning previously known effects of freezing precipitation on the stability and control characteristics, autopilot and related operational procedures when the ATR-72 was operated in such conditions. The French Directorate General Civil Aviation's inadequate oversight of the ATR-42~~

and 72 and its failure to take the necessary corrective action to ensure continued airworthiness in icing conditions

[0229][0228] 13. Date: Oct. 31, 1999 Location: Nantucket Island, Mass. Massachusetts Airline: Egypt Air Aircraft: Boeing 767-300ER Registration: SU-GAP Fatalities/No. Aboard: 217:217 Details: The plane took off from JFK at 4:19 a.m. bound for Cairo, Egypt. Thirty-three minutes later, after attaining an altitude of 33,000 feet, it was observed on radar in an extremely rapid descent and crashed seconds later into the Atlantic Ocean, 60 miles southeast of Nantucket Island. The aircraft was named Thutmosis III. There are strong indications one of the co-pilots committed suicide.

[0230][0229] 14. Dec. 19, 1997 Location: Palembang, Indonesia Airline: Silk Air SilkAir Aircraft: Boeing 737-300 Registration: 9V-TRF Fatalities/No. Aboard: 104:104 Details: The aircraft was on a flight from Jakarta to Singapore. The plane disappeared off radar screens and shortly after, crashed into the Musi River. The plane, almost brand new, cruising in good weather and with an experienced crew suddenly left normal flight from 35,000 feet and crashed at a high rate of speed into the Sumatran jungle. The right wing and parts of the rudder separated from the aircraft before it crashed. The Indonesian National Transportation Committee found that there was insufficient evidence to find a cause for the accident. The U.S. National Transportation Safety Board strongly disagreed and stated the jet's cockpit voice recorder was intentionally disconnected and its flight controls placed in a nose-down position most likely by the captain. While the U.S. NTSB stopped short of using the term suicide, its dissenting report made it clear it believed the crash was the result of actions by the captain.

[0231][0230] 15. Date: Aug. 21, 1994 Location: Agadir, Morocco Airline: Royal Air Maroc Aircraft: Aerospatiale ATR-42-300 Registration: CN-GDT Fatalities/No. Aboard: 44:44 Details: The aircraft entered a steep dive and crashed 10 minutes after takeoff from Agadir. The pilot was blamed for disconnecting the

~~autopilot and deliberately causing the crash and committing suicide. This was challenged by the Moroccan Pilot's Union.~~

5 ~~[0232][0231] 16. Date: Mar. 1, 1988 Location: Johannesburg, South Africa Airline: Commercial Airways Aircraft: Embraer EMB 11 OP1 EMB 110P1 Registration: ZS-LGP Fatalities/No. Aboard: 17:17 Details: The aircraft crashed and burned 8 miles from Jan Smuts Airport while attempting attempting to land. Detonation of a bomb consisting of nitro glycerin nitro glycerine and ammonium nitrate. A mineworker who heavily insured himself was thought to have committed suicide.~~

10 ~~[0233][0232] 17. Date: Aug. 12, 1985 Location: Mt. Osutaka, near Ueno Village, Japan Airline: Japan Airlines Aircraft: Boeing 747 SR46 Registration: JA81 19 JA8119 Fatalities/No. Aboard: 520:524 Details: The aircraft suffered an aft pressure bulkhead failure at 24,000 ft. after takeoff. The aircraft had severe control difficulties and eventually collided with a mountain. Improper repair of~~
15 ~~bulkhead by Boeing after a tail strike in 1978. Worst single plane disaster in aviation history. Kyu Sakamoto, 43, famous for his Japanese song "Sukiyaki" was killed in the accident. The Boeing official who had approved the repair committed suicide after the accident.~~

20 ~~[0234][0233] 18. Date: Dec. 15, 1997 Location: Sharjah, United Arab Emirates Airline: Tajikistan Airlines Aircraft: Tupolev TU 154 Registration: EY-85281 Fatalities/No. Aboard: 85:86 Details: The aircraft crashed and burned while making an attempt to land. A number of errors by the crew resulted in the accident accident. Not maintaining the height indicated during the last contact with the ATC, not following instructions from the ATC, crew fatigue, and turbulence in the~~
25 ~~area contributed to the accident~~

~~[0235][0234] 19. Date: May. 7, 1981 Location: Rio de la Plata, Argentina Airline: Austral Lineas Aeras Aircraft: BAC One Eleven 529FR Registration: LV-LOX Fatalities/No. Aboard: 31:31 Details: The aircraft crashed into a riverbed after two missed approaches and while in a holding pattern. Severe~~

~~turbulence and thunderstorms where occurring in area. Loss of control of the aircraft and impact with the water by an error of the pilot in assessing the meteorological conditions on crossing through a zone of extremely violent cumulonimbus clouds.~~

5 ~~[0236][0235] 20. Date: Oct. 27, 1972 Location: Noiretable, Loire, France Airline: Air Inter Aircraft: Vickers Viscount 724 Registration: F-BMCH Fatalities/No. Aboard: 60:68 Details: Crashed while landing in severe turbulence. Faulty indication by radio compass.~~

~~[0237][0236] 21. Date: Jul. 23, 1999 Location: Tokyo, Japan Airline: All Nippon Airways Aircraft: Boeing 747-400 Registration: Fatalities/No. Aboard: 10 4:517 Details: Two minutes after taking off Haneda Airport, a man carrying a knife forced a flight attendant to take him in the cockpit of the plane. A fan of computer flight simulation games, he stated he just wanted to fly a real plane. After forcing the co-pilot out of the cockpit he ordered the captain to fly to a U.S. Air Force base 15 in western Tokyo. When he refused, he stabbed the captain and seized the controls. After a sudden drop in altitude, the co-pilot and an off-duty crew member entered the cockpit and overpowered the hijacker. The plane landed safely but the captain died.~~

~~[0238][0237] 22. Date of Accident: 23 Nov. 1996 Airline: Ethiopian 20 Airlines Aircraft: Boeing 767-260ER Location: Comoros Islands, Madagascar Registration: ET-AIZ Previous Registrations: N6009F Flight Number: 961 Fatalities: 125:175 MSN: 23916 Line Number: 187 Engine Manufacturer: Pratt & Whitney Engine Model: JT9D-7R4E Year of Delivery: 1987 Accident Description: The aircraft crashed into the sea while attempting an emergency landing at Moroni 25 after running out of fuel. Hijackers who had read on the safety card that the airplane had a range of "12 hours" demanded to be flown to Australia, and ignored repeated warnings from the pilots that the aircraft did not have enough fuel.~~

~~[0239][0238] 23. Date: Oct. 2, 1990 Location: Guangzhou, China Airline: Xiamen Airlines/China Airlines / China Southwest Airlines Aircraft: Boeing~~

~~737-200/Boeing 737-200 / Boeing 757-200 Registration: B-2510/B-2812 B-2510 /
B-2812 Fatalities/No. Aboard: 128:226 Details: Shortly after takeoff a hijacker
entered the cockpit and demanded to be flown to Hong Kong. The captain circled
for 30 minutes and landed at Guangzhou, hitting the runway hard, clipping a B-707
5 and crashing into a B-757. Eighty-two aboard the B-737 and 46 aboard the B-757
were killed.~~

~~[0240][0239] 24. Date: Apr. 26, 1994 Location: Komaki, Aichi, Japan
Airline: China Airlines Aircraft: Airbus A300-600R Registration: B-1816
Fatalities/No. Aboard: 264:271 Details: While on ILS approach to Nagoya Airport,
10 at an altitude of 1,000 feet, the first officer inadvertently triggered the TOGA (take-
off go-around) lever. The crew tried to override this situation by turning off the auto
throttle and reducing air speed. The aircraft stalled, hit the runway tail first and
burst into flames. The plane crashed because of an extreme out of trim
configuration brought about by the fact that the tail plane setting had moved
15 automatically and undetected to a maximum nose-up position. The plane climbed
at a steep angle until it stalled. The crew could have saved the aircraft even in the
final seconds had they reverted to basic flight procedures and switched off the
autopilot.~~

~~[0241][0240] 25. Date: Mar. 10, 1989 Location: Dryden, Ontario,
20 Canada Airline: Air Ontario Aircraft: Fokker F-28 Fellowship 1000 Registration: C-
FONF Fatalities/No. Aboard: 24:69 Details: While flying from Thunder Bay, Ontario
to Winnipeg, Manitoba, the plane crashed on take-off from Dryden, Ontario. The
aircraft failed to gain altitude, settled back down on the runway and then took off
for a second time clipping the tops of trees, causing debris to clog the engines
25 leading to the plane crashing. The aircraft was being refueled with one engine
running because of an unserviceable APU. Since no external power unit was
available at the airport the engine could not be shut down and deicing could not be
performed. The captain's decision to take off in deteriorating weather conditions
with an accumulation of snow and ice on the wings. Decision not to de-ice the~~

~~plane before taking off. The failure of the Canadian air transport system in placing the crew in a situation where they did not have the resources to make a proper decision.~~

~~[0242][0241] 26. Date: Jul. 3, 2001 Location: Irkutsk, Russia Airline: Vladivostokavia Aircraft: Tupolev TU-154M Registration: RA-85845 Fatalities/No. Aboard: 145:145 Details: The aircraft crashed and exploded in flames in Siberian woodlands near the village of Burdakovka, about 21 miles from Irkutsk. The crash occurred as the plane was making its third land attempt at Irkutsk after abandoning two previous landing attempts. While flying at 2,800 ft., the aircraft suddenly made a 180-degree turn and plunged to the ground. The plane was scheduled to land at Irkutsk as an intermediate stop to refuel. Preliminary indications are that all three engine failed at once. This is the 59th worst accident in civil aviation history.~~

~~[0243][0242] 27. Date: Aug. 25, 2000 Location: Hilo Bay, Hi. Hawaii Airline: Big Island Air Aircraft: Piper PA-31-350 Navajo Chieftain Registration: N923BA Fatalities/No. Aboard: 1:9 Details: The aircraft, on an around the island tour and with its right engine on fire, ditched into Hilo Bay while attempting an emergency landing at Hilo International Airport. Eight people escaped from the plane before it sank in 100 feet of water. One passenger was not able to exit the plane and drowned. Possible failure of the turbo unit on the right engine.~~

~~[0244][0243] 28. Date: Aug. 12, 2000 Location: Tshikapa, Congo Airline: Staer Air Aircraft: Antonov AN-26B Registration: Fatalities/No. Aboard: 27:27 Details: The plane was approaching Tshikapa and the pilot informed the tower that it was having difficulties with its landing gear. The tower told the pilot to do a low fly by for an evaluation and then make an emergency landing but the pilot refused and attempted to return to Kinshasa. The plane crashed 40 miles north of Tshikapa.~~

~~[0245][0244] 29. Date: Jul. 17, 2000 Location: Patna, India Airline: Alliance Airlines Aircraft: Boeing 737-200 Advanced Registration: VT-EGD Fatalities/No. Aboard: 52:58+5 Details: While attempting to land at Patna, the~~

~~aircraft was too high and the crew attempted a go-around. During the second landing attempt the aircraft was again high, veered to left and lost altitude until it crashed into houses in the Gardanibagh district and burst into flames.~~

~~[0246][0245] 30. Date: Apr. 19, 2000 Location: Samal Island, Philippines Airline: Air Philippines Aircraft: Boeing 737-200 Registration: RP-C3010 Fatalities/No. Aboard: 131:131 Details: The aircraft circled Davao airport in an attempt to land but crashed onto a coconut plantation on the mountainous Samal Island. The plane aborted a previous landing attempt because another plane was on the runway. Weather and visibility were good in the area but the landing attempt may have been hampered by low-lying clouds. The last message from the crew was that they were 7 miles from the airport on final approach. Nothing more was heard from the plane. The aircraft disintegrated upon impact near Mt. Kalangan. The elevation of the accident site was about 500 feet above sea level but the plane should have been at an altitude of 1,500 feet.~~

~~15 [0247][0246] 31. Date: Jan. 31, 2000 Location: Point Mugu, California Airline: Alaska Airlines Aircraft: McDonnell Douglas MD-80 (MD-83) Registration: N963AS Fatalities/No. Aboard: 88:88 Details: The aircraft crashed into the Pacific Ocean south of Point Mugu while en route from Puerto Vallarta to San Francisco. Radio transmissions from the plane indicated the pilots were struggling with a jammed stabilizer for the last 11 minutes of the flight before nose-diving into the ocean. The crew was attempting to divert to LAX for an emergency landing when it crashed into the ocean.~~

~~25 [0248][0247] 32. Date: Dec. 21, 1999 Location: Guatemala City, Guatemala Airline: Cubana de Aviacon Aircraft: McDonnell Douglas DC-10-30 Registration: F-GTDI (aircraft leased by French AOM) Fatalities/No. Aboard: 17:314+9 Details: While attempting to land at La Aurora International Airport, the aircraft overshot the runway, rolled down an embankment and crashed into houses in the La Libertad section of the city. Witnesses say the plane was unable to stop after it began its landing too far down the runway.~~

~~[0249][0248] 33. Date of Accident: 28 Nov. 1979 Airline: Air New Zealand Aircraft: McDonnell Douglas DC 10-30 Location: Mt. Erebus, Antarctica Registration: ZK-NZP Previous Registrations: None Flight Number: 901 Fatalities: 257:257 MSN: 46910 Line Number: 182 Engine Manufacturer: General Electric~~
5 ~~Engine Model: CF6-50C2 Year of Delivery: 1974 Accident Description: The aircraft crashed into Mt. Erebus after dispatch inadvertently gave the flight crew the improper flight plan.~~

~~[0250][0249] 34. Date of Accident: 28 Jan. 2002 Airline: Transportes Aereos Aéreos Militares Ecuatorianos Aircraft: Boeing 727-134 Location: Cumbal~~
10 ~~Volcano, Colombia Registration: HC-BLF Previous Registrations: SE-DDB, RP-G1241, FAE692 Flight Number: 120 Fatalities: 92:92 MSN: 19692 Line Number: 498 Engine Manufacturer: Pratt & Whitney Engine Model: JT8D-9A Year of Delivery: 1967 Accident Description: TAME flight 120 departed Quito at 10:03 am on the first leg of its scheduled Quito-Tulcán-Cali Quito-Tulcan-Cali (Colombia)~~
15 ~~flight. Radio contact with the aircraft was lost at 10:23 am as it approached Tulcan Tulcán. The aircraft crashed near the Colombian city of Ipiales, Appeals, approximately 20 miles north of Tulcan Tulcán, in a crater near the top of the 15,626 ft Cumbal Volcano. The wreckage of the aircraft was found by aerial search some 24 hours after the initial disappearance of the plane. The weather in the~~
20 ~~heavily mountainous region was reported to be foggy around the time of the accident.~~

~~[0251][0250] 35. Date of Accident: 08 Oct. 2001 Airline: Scandinavian Airlines (SAS) Aircraft: McDonnell Douglas MD-87 Location: Milan, Italy Linate Italy Linate Airport Registration: SE-DMA Previous Registrations: Not~~
25 ~~Available Flight Number: 686 Fatalities: 118:118+4 MSN: 53009 Line Number: 1916 Engine Manufacturer: Not Available Engine Model: Not Available Year of Delivery: 1991 Accident Description: Scandinavian SK686, on a flight from Milan to Copenhagen, was cleared to taxi to Runway runway 36R for departure. At approximately the same time, a German Cessna Citation II business jet (D-IEVX),~~

was cleared to taxi from the General Aviation ramp via taxiway Romeo 5. The Citation mistakenly entered taxiway Romeo 6, entered runway 36R, and at that point was impacted by SK686 which had been cleared for takeoff. Both aircraft broke up, skidded to the right of the active runway, and impacted an airport baggage hangar, which partially collapsed. Weather at the time of the accident was reported as "heavy fog" with a Runway runway 36R RVR (runway visual range) of 225 meters.

[0252][0251] 36. Date of Accident: 30 Jan. 2000 Airline: Kenya Airways Aircraft: Airbus A310-304 Location: Abidjan, Ivory Coast, Africa
10 Registration: 5Y-BEN Previous Registrations: F-WWCK Flight Number: 431 Fatalities: 169:179 MSN: 416 Line Number: Not Available Engine Manufacturer: General Electric Engine Model: CF6-80C2A2 Year of Delivery: 1986 Accident Description: The aircraft crashed into the Atlantic Ocean shortly after takeoff from Abidjan. Numerous eyewitnesses who saw the airplane takeoff reported that it
15 failed to gain altitude and struck the water around a mile from the runway. 10 survivors were pulled from the water by rescue boats. The probable cause of the accident was determined to be 'the aerodynamic stall warning which falsely indicated that the plane had stalled moments after takeoff, and the Captain's failure to properly react to a false alarm. Contributing to the accident was the plane's
20 takeoff at night over water.'

[0253][0252] 37. Date of Accident: 06 Aug. 1997 Airline: Korean Air Lines Aircraft: Boeing 747-3B5 Location: Agana, Guam Registration: HL7468 Previous Registrations: N6069D Flight Number: 801 Fatalities: 228:254 MSN: 22487 Line Number: 605 Engine Manufacturer: Pratt & Whitney Engine Model: JT9D-7R4G2 Year of Delivery: 1984 Accident Description: The aircraft crashed
25 while executing a non-precision localizer approach to runway 6R at Agana. The crew descended below the approach profile, and struck terrain approximately 3 miles short of the runway. The crew did not understand that the glideslope of the ILS system was out of service.

[0254][0253] 38. Date of Accident: 19 Dec. 1997 Airline: SilkAir
Aircraft: Boeing 737-36N Location: Palembang, Indonesia Registration: 9V-TRF
Previous Registrations: None Flight Number: 185 Fatalities: 104:104 MSN: 028556
Line Number: 2851 Engine Manufacturer: CFM International Engine Model:
5 CFM56-3B2 Year of Delivery: 1997 Accident Description: The aircraft abruptly
entered a descent and crashed during cruise. The cockpit voice recorder was
turned off before the descent. It is believed that the Captain committed suicide.

[0255][0254] 39. Date of Accident: 12 Nov. 1996 Airline: Saudi
Arabian Airlines Aircraft: Boeing 747-168B Location: Chaki Dahdri, India
10 Registration: HZ-AIH Previous Registrations: Not Available Flight Number: 763
Fatalities: 312:312 MSN: 22748 Line Number: 555 Engine Manufacturer: Rolls
Royce Engine Model: RB211-524G2 Year of Delivery: 1982 Accident Description:
The aircraft crashed after colliding with a Kazastan Airlines Ilyushin Ilyushin that
had not maintained its assigned altitude. Error on the part of the Ilyushin Ilyushin
15 crew. Deadliest mid-air collision in aviation history.

[0256][0255] 40. Date of Accident: 31 Jul. 1992 Airline: Thai Airways
Aircraft: Airbus A310-304 Location: Kathmandu, Nepal Registration: HS-TID
Previous Registrations: F-WWCE, C-FGWD Flight Number: 311 Fatalities: 113:113
MSN: 438 Line Number: Not Available Engine Manufacturer: General Electric
20 Engine Model: CF6-80C2A2 Year of Delivery: 1987 Accident Description: After
experiencing a flap problem while attempting to extend the flaps fully on a seven
mile final, the crew requested a missed approach and it was approved. The radar
at Kathmandu was inoperative due to maintenance work, and the aircraft turned
toward the south toward rising terrain. The Captain ignored the ground proximity
25 warning system thinking it was a false alarm. Crew error in not following the
published missed approach procedure.

[0257][0256] 41. Date of Accident: 27 Aug. 1992 Airline: Aeroflot
Aircraft: Tupolev TU-134A Location: Ivanovo, Russia Registration: SSSR-65058
Previous Registrations: Not Available Flight Number: 2808 Fatalities: 84:84 MSN:

~~49868 Line Number: Not Available Engine Manufacturer: Not Available Engine Model: Not Available Year of Delivery: Not Available Accident Description: The aircraft crashed short of the runway while executing an instrument approach. Pilot error.~~

5 ~~[0258][0257] 42. Date of Accident: 06 Jun. 1992 Airline: COPA Aircraft: Boeing 737 204 Location: Tucuti, Panama Registration: HP 1205 Previous Registrations: N8985V, G BGYL Flight Number: 201 Fatalities: 47:47 MSN: 22059 Line Number: 743 Engine Manufacturer: Pratt & Whitney Engine Model: JT8D 15 Year of Delivery: 1980 Accident Description: The aircraft crashed after malfunction~~
10 ~~in the artificial horizons. A wire from the gyroscopes to the instruments themselves had frayed, creating a short, and erroneous attitude indications. Flying VFR at night over woodland, the crew was unable to determine that aircraft's attitude, and the wings rolled past 90.degree. 90° bank. The plane then entered a steep dive and broke up at approximately 13,000 feet.~~

15 ~~[0259][0258] 43. Date of Accident: 25 Jan. 1990 Airline: Avianca Aircraft: Boeing 707 321 B 707 321B Location: Cove Neck, N.Y. New York Registration: HK 2016 Previous Registrations: N423PA Flight Number: 52 Fatalities: 73:158 MSN: 19276 Line Number: 592 Engine Manufacturer: Pratt & Whitney Engine Model: JT3D 3B Year of Delivery: 1967 Accident Description: The~~
20 ~~aircraft crashed while in a holding pattern awaiting landing at New York's Kennedy Airport. After an unsuccessful approach in bad weather, the crew executed a missed approach and was put into holding. The First Officer declared 'minimum fuel' to ATC but never declared an emergency, which would have given the aircraft immediate clearance to land. Crew error.~~

25 ~~[0260][0259] 44. Date of Accident: 08 Feb. 1989 Airline: Independent Air Aircraft: Boeing 707 331 B 707 331B Location: Santa Maria, Azores, Portugal Registration: N7231T Previous Registrations: N28727 Flight Number: 1851 Fatalities: 144:144 MSN: 19572 Line Number: 687 Engine Manufacturer: Pratt & Whitney Engine Model: JT3D 3B (HK) Year of Delivery: 1968 Accident Description:~~

~~The aircraft impacted terrain after being given an improper vector by air traffic control. ATC error.~~

~~[0261][0260] 45. Date of Accident: 07 Jun. 1989 Airline: Suriname Airways Aircraft: McDonnell Douglas DC-8-62 Location: Paramaribo, Surinam
5 Registration: N1809E Previous Registrations: None Flight Number: 764 Fatalities: 176:187 MSN: 46107 Line Number: 498 Engine Manufacturer: Pratt & Whitney Engine Model: JT3D Year of Delivery: 1969 Accident Description: The aircraft impacted trees after the crew descended below MDA in an attempt to make visual contact with the runway during their third approach. Crew fatigue, low fuel situation
10 that which necessitated landing immediately.~~

~~[0262][0261] 46. Date of Accident: 16 Aug. 1987 Airline: Northwest Airlines Aircraft: McDonnell Douglas MD-82 Location: Romulus, Mich. Michigan (Detroit Airport) Registration: N312RC Previous Registrations: N1004F Flight Number: 255 Fatalities: 154:155+2 154:155 + 2 MSN: 48090 Line Number: 1040
15 Engine Manufacturer: Pratt & Whitney Engine Model: JT8D-217 Year of Delivery: 1982 Accident Description: The aircraft crashed on takeoff from Detroit's Wayne County Airport. Examination of the Cockpit Voice Recorder revealed that, in a rush to depart, the crew never completed the Before Takeoff checklist. Among other items, the aircraft's slats and flaps were not configured for departure. The aircraft
20 clipped several light posts, impacted the top of a rental car building, and came to rest inverted on the airport entrance roadway.~~

~~[0263][0262] 47. Date of Accident: 07 Dec. 1987 Airline: Pacific Southwest Airlines Aircraft: British Aerospace BAe-146 Location: San Luis Obispo, Calif. California Registration: N350PS Previous Registrations: Not Available Flight
25 Number: 1771 Fatalities: 43:43 MSN: Not Available Line Number: Not Available Engine Manufacturer: Not Available Engine Model: Not Available Year of Delivery: Not Available Accident Description: US Air employee David Burke, recently fired for stealing money from a 'beer fund' kept by Flight Attendants, used his airport clearance to gain access to the aircraft, on which the US Air CEO was flying,~~

without going through a security checkpoint. Upon reaching cruise altitude, Burke dropped a hand-written note into the US Air CEO's lap reading 'It's kind of ironical, isn't it? I asked for leniency for my family, remember? Well, I got none, and now you'll get none.' Burke then proceeded to the cockpit with a loaded 0.44 .44, shot
5 both pilots, and put the aircraft into a steep dive from which it would never recover.

[0264][0263] 48. Date of Accident: 13 Jul. 1973 Airline: Delta Air
Lines Aircraft: McDonnell Douglas DC 9-31 Location: Boston, Mass.
Massachusetts, USA Registration: N975NE Previous Registrations: None Flight
Number: 723 Fatalities: 89:89 MSN: 47075 Line Number: 166 Engine
10 Manufacturer: Pratt & Whitney Engine Model: JT8D Year of Delivery: 1967
Accident Description: The aircraft crashed into a seawall while attempting the ILS
15L approach at Logan International Airport. Air Traffic Control was faulted for
vectoring the airplane to only a 4-mile final for the approach, and the crew was
faulted for continuing the approach with insufficient time to stabilize the aircraft on
15 final.

[0265][0264] 49. Date of Accident: 06 Oct. 1955 Airline: United
Airlines Aircraft: Douglas DC-4 Location: Centennial, Wyo. Wyoming, USA
Registration: N30062 Previous Registrations: Not Available Flight Number: 409
Fatalities: 66:66 MSN: 18389 Line Number: Not Available Engine Manufacturer:
20 Not Available Engine Model: Not Available Year of Delivery: Not Available Accident
Description: The aircraft crashed after the pilots became incapacitated from carbon
monoxide leaking from a faulty cabin heater.

[0266][0265] 50. Date of Accident: 30 Jun. 1956 Airline: United
Airlines Aircraft: Douglas DC-7 Location: Grand Canyon, Ariz. Arizona, USA
25 Registration: N6902C Previous Registrations: Not Available Flight Number: 718
Fatalities: 58:58 MSN: 44288 Line Number: Not Available Engine Manufacturer:
Not Available Engine Model: Not Available Year of Delivery: Not Available Accident
Description: The aircraft, on a flight from Los Angeles to Chicago, collided with a
TWA Lockheed Super Connie over the Grand Canyon in VFR conditions. Inability

~~for both pilots to see the other aircraft in uncontrolled airspace under VFR was cited as the primary cause of the accident.~~

~~[0267][0266] 51. Date of Accident: 05 Mar. 2000 Airline: Southwest Airlines Aircraft: Boeing 737-3T5 Location: Burbank, Calif. California, USA~~
5 ~~Registration: N668SW Previous Registrations: G-BLKB, N753MA Flight Number: 1455 Fatalities: 0:142 MSN: 23060 Line Number: 1069 Engine Manufacturer: CFM International Engine Model: CFM56-3B1 Year of Delivery: 1985 Accident Description: Arriving in Burbank on a flight from Las Vegas, Nev. NV, the crew contacted SOCAL Approach and were told to expect the visual approach to~~
10 ~~runway 8 at BUR. Approximately 10 miles from the field, while descending to 3000 feet, the crew was instructed to maintain 230 knots until further advised. One minute later, the crew was cleared for the visual approach to runway 8, with an instruction to maintain 3,000 feet until passing the Van Nuys VOR (approx 6 nm from the runway). For unknown reasons, the flight crew passed the VOR and failed~~
15 ~~to start their descent from 3000 feet. 3.9 nm from the runway threshold, at an airspeed of 230 knots and an altitude of 3000 feet, the crew began their descent to land. Due to the steep nature of the descent (nearly 70 7°), the crew received two "sink rate" warnings at approximately 400' AGL, and a "pull up" warning at 190' AGL. The aircraft touched down 2800' down the 6032' runway with a groundspeed~~
20 ~~of 181 knots. Despite using max reverse thrust, spoilers, and brakes, the crew was unable to stop the aircraft before the end of the runway. The plane broke through a blast fence at approximately 40 knots, skidded across Hollywood Way, and came to rest 38' from a Chevron gasoline station. The aircraft was evacuated via the escape slides.~~

25 ~~[0268][0267] 52. Date: Mar. 27, 1977 Time: 17:07 Location: Tenerife, Canary Islands Airline: Pan American World Airways/KLM Airways / KLM Flight #: 1736/4805 AC Type: Boeing B-747-121/Boeing B-747-121 / Boeing B-747-206B Registration: N736PA/PH-BUF en/in: 19643/20400 A19643 / 20400 board: 644 Fatalities: 583 Ground: 0 Details: Both aircraft were diverted to Tenerife because~~

of a bombing at Las Palmas Airport. After an extended delay, both planes were instructed to back track up the runway. The KLM plane reached its takeoff point while the Pan Am plane was still on the runway. The Pan Am plane continued up the runway missing the taxiway turnout. There was heavy fog on the runway. The KLM plane began its takeoff roll without permission with the Pan Am plane still on the runway. The KLM plane hit the Pan Am plane just as it was taking off. Both planes burst into flames. This was the worst death toll in aviation history. KLM 234+14 234 + 14 crew, Pan Am 326+9 326 + 9 crew killed. The Pan Am aircraft was named Victor.

10 [0269][0268] 53. Date: Oct. 8, 2001 Location: Milan, Italy Airline: Scandinavian Airlines System (SAS) Aircraft: McDonnell Douglas MD-80 (MD-87) Registration: SE-DMA Fatalities/No. Aboard: 114:114+4 114:114 +4 Details: The aircraft was taking off from Linate Airport in fog and poor visibility when it struck a German Cessna Citation II business jet. The MD-87 then swerved off the runway and collided with the airport's baggage handling building, bursting into flames. The Cessna, which was about to take off for Paris, entered the active runway by mistake, after having been told by the tower to enter a different runway. One hundred four passengers and 6 crew killed on the MD-87, 2 passengers and 2 crew killed on the Citation and 4 killed on the ground.

20 [0270][0269] 54. Date: Oct. 31, 2000 Location: Taipei, Taiwan Airline: Singapore Airlines Aircraft: Boeing 747-400 Registration: 9V-SPK Fatalities/No. Aboard: 83:179 Details: The aircraft began its takeoff roll in heavy rain and high winds. The pilot mistakenly tried to take off on a closed runway and the aircraft struck construction equipment, broke in three and burst into flames. The pilot missed some key warnings, including a routine preflight briefing report that warned of the hazard on the runway under construction and two signs indicating the number of the runway he mistakenly went down

25 [0271][0270] 55. Date: Nov. 22, 1994 11/22/1994 Location: Bridgeton, Mo. Missouri Airline: TWA Trans World Airlines/Private Airlines / Private

~~Aircraft: McDonnell Douglas Super MD 80 (MD 82)/Cessna (MD 82) / Cessna 441~~

~~Registration: N954U/N411 KM N954U / N411KM Fatalities/No. Aboard: 2:142~~

~~Details: During its takeoff roll, the DC 9 collided with the Cessna, which was waiting for clearance to take off. The ground collision took place in the fog. The~~

- 5 ~~Cessna pilot mistakenly thought he had clearance to enter the runway. Two aboard the Cessna were killed, none were killed aboard the DC 9.~~

~~[0272][0271] 56. Date: Nov. 21, 1990 Location: Koh Samui, Thailand~~

~~Airline: Bangkok Airways Aircraft: de Havilland Canada Dash 8 103 Registration:~~

~~OB 1358 Fatalities/No. Aboard: 38:38 Details: After receiving a runway change,~~

- 10 ~~the crew executed a missed approach. They became confused on which way to go. They entered an area of clouds and heavy rain, became disoriented and descended in a left wing down attitude until they impacted the ground at a coconut plantation. The pilots experienced spatial disorientation which resulted in improper control of the aircraft. Numerous procedural errors and poor cockpit discipline by~~

- 15 ~~the crew.~~

~~[0273][0272] 57. Date: Jan. 30, 1975 Location: Istanbul, Turkey~~

~~Airline: THY Turkish Airlines Aircraft: Fokker F 28 Fellowship fellowship 1000~~

~~Registration: TC JAP Fatalities/No. Aboard: 42:42 Details: After an electrical failure at the airport the aircraft initiated a go around. Because another aircraft was about~~

- 20 ~~to take off, an extended downwind leg was flown. The aircraft crashed into the Sea of Marmara while in the process of making the second approach.~~

~~[0274][0273] 58. Date: Oct. 13, 1973 Location: Domodedovo, Russia,~~

~~USSR Airline: Aeroflot Aircraft: Tupolev TU 104B Registration: SSSR 42486~~

~~Fatalities/No. Aboard: 119:119 Details: After making a right turn, the aircraft~~

- 25 ~~plunged to earth from 1,500 ft. Electrical failure of compass and main gyro.~~

~~[0275][0274] 59. Broken Arrow On Jan. 17, 1966, an SAC B 52 had a~~

~~mid-air collision with a KC 135 tanker while refueling over Palomares, Spain. The~~

~~B 52 was carrying four thermonuclear B28 bombs. The bomber had begun the~~

~~mission at Seymour Johnson AFB, N.C North Carolina. The KC 135 had come~~

from the Moron Air Base, Spain. All four KC 135 crew members were killed, while four of the seven B 52 crew parachuted to safety. President Lyndon Johnson, the Department of Defense, the Atomic Energy Commission, and the Spanish Government received news of the nuclear accident. Nuclear safety teams were dispatched immediately. Within hours, the 16th Air Force had located the three B28 bombs that landed on the shore. However, the fourth bomb was missing; it was not found for 80 days. High explosives in two bombs had detonated on impact. Plutonium dust had spread over several hundred acres. One reassuring fact emerged from this incident: inherent safety features designed and built by Atomic Energy Commission contractors ensured that no nuclear explosion occurred.

[0276][0275] 60. Date: Nov. 7, 1996 Location: Lagos, Nigeria Airline: Aviation Development Corporation Aircraft: Boeing 727-200 Registration: 5N-BBF Fatalities/No. Aboard: 143:143 Details: The plane crashed mid-way along its scheduled 50 minute route. The aircraft went into a roll and lost control after taking evasive action to avoid another aircraft. The plane was flying almost at the speed of sound when it crashed and disintegrated. ATC error.

[0277][0276] 61. Date: Feb. 1, 1991 Location: Los Angeles, Calif. Airline: USAir/Skywest Airlines California Airline: USAir / Skywest Airlines Aircraft: Boeing 737-300/Swearingen 737-300 / Swearingen SA 27AC Registration: N388US/N683AV N388US / N683AV Fatalities/No. Aboard: 34:99 Details: The Skywest Metroliner was told to taxi into position for takeoff and hold. The ATC became preoccupied with another aircraft that departed the tower frequency. A Wings West aircraft reporting "ready for takeoff", caused some confusion because the controller didn't have a flight progress strip in front of her. The strip appeared to have been misfiled at the clearance delivery position. The USAir, which was cleared to land, landed on top of the Metroliner. After the collision, both planes slid off the runway into an unoccupied fire station and burst into flames. The failure of the Los Angeles Air Traffic Facility Management to implement procedures that

provided redundancy comparable to the requirements contained in the National Operational Position Standards and the failure of the FAA ATS to provide adequate policy direction and oversight to its ATC facility managers. These failures created an environment in the Los Angeles ATC tower that ultimately led to the failure of the controller to maintain awareness of the traffic situation, culminating in the inappropriate clearances and the subsequent collision of the USAir and SkyWest aircraft. Twenty two killed aboard the USAir, 12 aboard the Metroliner

5 [0278][0277] 62. Date: Sep. 25, 1978 Location: San Diego, Calif.
California Airline: Pacific Southwest Airlines/Private Airlines / Private Aircraft:
10 Boeing 727-200/Cessna 727-200 / Cessna 172 Registration: N533PS/N7711-G
N533PS / N7711G Fatalities/No. Aboard: 137:137+7 137:137 +7 Details: Midair collision. The PSA was descending and about to land at Lindbergh Field. The Cessna was climbing while engaged in practice approaches. The 727 overtook and struck the Cessna from the rear. The primary cause was the PSA crew lost
15 sight of the Cessna and did not make that fact known to the ATC. The ATC failed to realize from the PSA transmissions that they lost sight of the Cessna. One hundred thirty five killed on the PSA, two on the Cessna seven on the ground. Crew fatigue may have played a part in the accident as there are unofficial reports that the crew attended an all night party and had only 2 hours sleep from the night
20 before.

[0279][0278] 63. Date: Sep. 10, 1976 Location: Gaj, Hrvatska, Yugoslavia Airline: Inex Adria Aviopromet/BAA Aviopromet / BAA British Airways Aircraft: Douglas DC-9-31/BAe DC-9-31 / BAe Trident 3B Registration: YU-AJR/G-AWZT YU-AJR / G-AWZT Fatalities/No. Aboard: 176:176 Details: Midair collision.
25 ATC error, negligence in operations. Improper look-out duties on both aircraft. One hundred thirteen deaths on the DC-9, 63 on the Trident. The entire shift of controllers were arrested. One was found guilty of criminal negligence and sentenced to seven years in jail but release after a little over two years.

~~[0280][0279] 64. Date: Sep. 9, 1976 Location: Adler, Russia, USSR
Airline: Aeroflot/Aeroflot Aeroflot / Aeroflot Aircraft: Antonov AN-24/Yakovlev AN-
24 / Yakovlev Yak 40 Registration: SSSR 46518/SSSR 87772 SSSR 46518 /
SSSR 87772 Fatalities/No. Aboard: 90:90 Details: Midair collision at FL1-87~~

- 5 ~~FL187. ATC error. Fifty-two deaths on the Antonov, 38 on the Yak. Violation of
separation rules. Contributing causes were insufficient visual alertness on the part
of both crews and a lack of 'situation analysis' based on air/ground radio
communications.~~

- ~~[0281][0280] 65. Date: Oct. 31, 2000 Location: Taipei, Taiwan Airline:
10 Singapore Airlines Aircraft: Boeing 747-400 Registration: 9V-SPK Fatalities/No.
Aboard: 83:179 Details: The aircraft began its takeoff roll in heavy rain and high
winds. The pilot mistakenly tried to take off on a closed runway and the aircraft
struck construction equipment, broke in three and burst into flames. The pilot
missed some key warnings, including a routine preflight briefing report that warned
15 of the hazard on the runway under construction and two signs indicating the
number of the runway he mistakenly went down.~~

- ~~[0282][0281] 66. Date: Jul. 25, 2000 Location: Gonesse, France
Airline: Air France Aircraft: Aerospatiale BAe Concorde 101 Registration: F-BTSC
Fatalities/No. Aboard: 109:109+5 Details: The aircraft struggled to gain altitude
20 after taking off from Charles de Gaulle airport. The pilot reported the No. 2 engine
failed and struggled to steer towards Le Bourget airfield as smoke and fire trailed
the jet's left wing. The plane was unable to gain altitude, went nose high, stalled
and crashed into a small hotel complex. Preliminary indications are a metal strip
left on the runway by another plane gashed one of the Concorde's tires which blew
25 out damaging a fuel tank and causing a leak. Leaking fuel ignited and started an
uncontrollable fire. Power was lost to the No. 1 No. 1 and No. 2 engines which led
to loss of control of the aircraft and subsequent crash. This is the first crash of a
Concorde in aviation history.~~

~~[0283][0282] 67. Date: Dec. 21, 1999 Location: Guatemala City,
Guatemala Airline: Cubana de Aviacon Aircraft: McDonnell Douglas DC 10-30
Registration: F-GTDI (aircraft leased by French AOM) Fatalities/No. Aboard:
17:314+9 Details: While attempting to land at La Aurora International Airport, the
5 aircraft overshot the runway, rolled down an embankment and crashed into houses
in the La Libertad section of the city. Witnesses say the plane was unable to stop
after it began its landing too far down the runway.~~

~~[0284][0283] 68. Date: Apr. 20, 1998 Location: Bogota, Colombia
Airline: Air France (operated by TAME) Aircraft: Boeing 727-200 Registration: HG-
10 BSU Fatalities/No. Aboard: 53:53 Details: The aircraft crashed atop fog-covered
Cerro el Cable mountain and exploded into flames, three minutes after taking off
from Bogota's El Dorado airport, en route to Quito. The aircraft was leased to Air
France by TAME airlines. The crew did not turn in the proper direction after
reaching the Romeo non-directional beacon even though the flight crew
15 acknowledged an air traffic controller's warning that they were off course.~~

~~[0285][0284] 69. Date: Oct. 2, 1996 Location: Pasamayo, Peru
Airline: Aeroperu Aircraft: Boeing 757-200 Registration: N52AW Fatalities/No.
Aboard: 70:70 Details: The aircraft crashed into the ocean 28 minutes after taking
off from Lima, Peru. Pieces of adhesive tape were found covering the static ports,
20 placed there by personnel during aircraft maintenance and cleaning, causing the
malfunction of the airspeed indicators and altimeters. The crew was not able to
correctly determine their altitude and airspeed and with no ground reference over
water and at night, crashed into the ocean. An employee did not remove the
adhesive tape from the static ports, nor was it detected by any number of people,
25 including the captain, during the preflight inspection A maintenance worker was
tried and convicted of negligent homicide for failing to remove the adhesive tape
and received 2 years in jail.~~

~~[0286][0285] 70. Date: May 24, 1995 Location: Harewood, S Yorks,
England Airline: Knight Air Aircraft: Embraer EMB-11-OP1 EMB-110P1~~

Bandeirante Registration: G-OEAA Fatalities/No. Aboard: 12:12 Details: The crew had serious problems maintaining their heading after both artificial horizons failed shortly after takeoff. The crew had difficulty controlling the aircraft in turbulence conditions and the plane went into a spiral dive and crashed into a field. One or possibly both of the aircraft's artificial horizons malfunctioned and in the absence of a standby horizon, for which there was no airworthiness requirement, there was no single instrument available for assured attitude reference or simple means of determining which flight instruments had failed. The pilot became spatially disoriented and was unable to maintain control.

10 [0287][0286] 71. Date: May 19, 1993 Location: Medellin, Colombia
Airline: SAM (Columbia) Aircraft: Boeing 727 Registration: HK-
2422.times.Fatalities/No. HK-2422X Fatalities/No. Aboard: 132:132 Details: The
plane hit Mt. Paramo Frontino at 12,300 ft. while on approach to Maria Cordova
Airport. Errors by the crew and the ATC. The aircraft descended into mountainous
15 mountaineous terrain before actually reaching the Abejorral NDB Beacon. The
VOR/DME had been sabotaged sabatoged by terrorists terorists and not in
service.

 [0288][0287] 72. Date: Nov. 24, 2001 Location: Birchwil, Switzerland
Airline: Crossair Aircraft: BAE Avro RJ100 Registration: HB-IXM Fatalities/No.
20 Aboard: 24:33 Details: The aircraft was flying through a mix of rain and snow on
final approach, when it crashed in a wooded area, 5.5 miles from Zurich Airport
where it was scheduled to land on Runway runway 28.

 [0289][0288] 73. Date: Nov. 19, 2001 Location: Kalyazin, Russia
Airline: Charter IRS Charter IRS Aero Aircraft: Ilyushin 11-18 Ilyushin II 18
25 Registration: RA-75840 Fatalities/No. Aboard: 27:27 Details: Residents heard a
loud noise and saw flames in the night sky as the aircraft clipped treetops and
summer homes before crashing into a snowy forest. Wreckage was spread over a
1.5 mile 1.5 mile area

~~[0290][0289] 74. Date: Oct. 10, 2001 Location: Dillingham, Alaska
Airline: PenAir Aircraft: Cessna 208 Caravan Registration: N9530F Fatalities/No.
Aboard: 9:10 Details: Shortly after taking off from Dillingham, the aircraft's wing
dipped, the nose pitched up, the plane became inverted and crashed to the
5 ground. The weather was clear and windy at the time of the accident.~~

~~[0291][0290] 75. Date: Oct. 4, 2001 Location: Sochi, Russia Airline:
Sibir Airlines Aircraft: Tupolev TU-154M Registration: RA-85693 Fatalities/No.
Aboard: 76:76 Details: The aircraft exploded in mid air at 36,000 ft. while en route
over the Black Sea. The plane then nose dived crashing into the water. It is
10 believed the airliner was brought down accidentally by a Ukrainian surface-to-air
missile, fired during military exercises.~~

~~[0292][0291] 76. Date: Sep. 18, 2001 Location: Guatemala City,
Guatemala Airline: Atlantic Airlines Aircraft: LET 41 OUV E 410UVP-E
Registration: TG-CPE Fatalities/No. Aboard: 8:13 Details: The aircraft was taking
15 off from Guatemala's Aurora Airport when it lost power in one of its engines and
crashed back to the ground.~~

~~[0293][0292] 77. Date: Sep. 15, 2001 Location: Belo Horizonte, Brazil
Airline: TAM Aircraft: Fokker F-28-100 Registration: PT-MRN Fatalities/No.
Aboard: 1:82 Details: While the aircraft was over Belo Horizonte, the cabin
20 depressurized, causing the death of one passenger. The aircraft made an
emergency landing at Cofins. Three of the other 77 passengers aboard suffered
minor injuries. Pressurization was lost at an altitude of 33,000 feet when the right
engine disintegrated, causing pieces of the engine to break two cabin windows~~

~~[0294][0293] 78. Date: Sep. 12, 2001 Location: Chichen Itza, Mexico
25 Airline Mexico Airline: Aero Ferinco Charter Aircraft: LET 410UVP Registration: XA-
ACM Fatalities/No. Aboard: 19:19 Details: The the aircraft crashed 4.4 miles from
Kura Airport shortly after a normal takeoff. The plane was flying at about 1,500 feet
when it began turning onto a course requested by the air traffic controller. It did not
stop turning and suddenly plunged to the ground. All the passengers killed were~~

Americans from the Cruise ship Massdam who had just finished visiting the Myan ruins at Chichen Itza.

[0295][0294] 79. Date: Sep. 11, 2001 Location: New York City, N.Y.
Airline New YorkAirline: United Airlines Aircraft: Boeing 767-200 Registration:
5 N612UA Fatalities/No. Aboard: 65:65+1 000s? Details 65:65 +1000s?Details: The aircraft was hijacked shortly after it left Logan International Airport in Boston and crashed into the south tower of the World Trade Center. The building subsequently collapsed. It was one of four planes hijacked by terrorists.

[0296][0295] 80. Date: Sep. 11, 2001 location: Buckstown, Pa.
10 Pennsylvania Airline: United Airlines Aircraft: Boeing 757-200 Registration: N591 UA Fatalities/No. Aboard: 45:45 Details: The aircraft was hijacked shortly after taking off from Newark International Airport. It changed direction began heading towards Washington when it crashed at a high rate of speed into a field in the Pennsylvania countryside. It was one of four planes hijacked by terrorists.

15 [0297][0296] 81. Date: Dec. 20, 1972 Location: Chicago, 111. Illinois
Airline: Delta Air Lines/North Central Airlines Lines / North Central Airlines Aircraft: Convair 880/Douglas 880 / Douglas DC-9-31 Registration: N8897E/N954N
N8897E / N954N Fatalities/No. Aboard: 10:133 Details: The Delta Convair taxiing across Runway runway 27L in heavy fog, was hit by the North Central DC-9 as it
20 took off. The DC-9 came crashing back down on the runway and caught fire. Ten people (all passengers) out of a total of 45 aboard the DC-9 were killed. None of the 88 aboard the Convair were killed. Failure of the ATC to ensure aircraft separation during restricted visibility.

[0298][0297] 82. INCIDENT Jan. 25, 2002 03:00 A China Airlines
25 Airbus A-340, Flight 011, carrying 254 passengers and crew members narrowly avoided catastrophe early Friday when pilots took off in the wrong direction and on taxiway kilo instead of Runway runway 32 at Ted Stevens Anchorage International Airport. The plane came so close to running out of taxiway that its landing gear

~~clipped a snow berm at the pavement's end before it gained altitude over Cook Inlet and flew on to Taipei. The incident is under investigation by the NTSB.~~

~~[0299][0298] 83. Date: Sep. 1, 1983 Time: c 06:30 Location 06:30
Location: Near Sakhalin Island, Russia Airline: Korean Airlines Flight #: 007AG
5 Type: Boeing B-747-230B Registration: HL-7442 en/In: 20599 Aboard HL-7442
en/In: 20599 Aboard: 269 Fatalities: 269 Ground 269 Ground: 0 Details: On a flight
from Alaska to South Korea, the airliner drifted off course and twice penetrated
Soviet airspace. During the second penetration, the airliner was shot down by a
Russian Su-15 Air Force fighter with air-to-air missiles. The aircraft crashed into
10 international waters in the Sea of Japan. U.S. Representative from Georgia
Lawrence McDonald killed.~~

~~[0300][0299] 84. Date: Aug. 10, 1994 Location: Cheju, South Korea
Airline: Korean Airlines Aircraft: Airbus A300-600R B4 Registration: HL-7296
Fatalities/No. Aboard: 0:160 Details: The aircraft overran the runway and caught
15 fire while landing during adverse weather conditions. The approach was flown with
slats/flaps at 15/20 degrees due to suspected windshear. Crew error. There was a
struggle and argument between the captain and copilot during the last seconds of
the landing as to whether they should go around.~~

~~[0300] 85. Location: Chardzhov, Russia, USSR. Airline: Aeroflot.
20 Aircraft: Yakovlev YAK-40. Registration: SSSR-78390. Fatalities/No. Aboard:
59:59. Details: The plane crashed after entering the wake turbulence of a
helicopter.~~

~~All of the above U.S. patents, U.S. patent application publications,
U.S. patent applications, foreign patents, foreign patent applications and non-
25 patent publications referred to in this specification and/or listed in the Application
Data Sheet, are incorporated herein by reference, in their entirety.~~

~~From the foregoing it will be appreciated that, although specific
embodiments of the invention have been described herein for purposes of
illustration, various modifications may be made without deviating from the spirit~~

and scope of the invention. Accordingly, the invention is not limited except as by the appended claims.

CLAIMS

1. A system, comprising: ~~An anti-crash system;~~Anti-Crash System; An auto-controlling and piloting system, receiving commands from said ~~anti-crash system;~~Anti-Crash System. A monitoring device system, communicating with said ~~anti-crash system;~~ ~~An authorities" security aircraft flight equipment computer;~~Anti-Crash System. An Authorities' Security Aircraft Flight Equipment (ASAFE) system, communicating with said Anti-Crash System,~~anti-crash system;~~ said auto-controlling and piloting system, and said monitoring system; and ~~A~~a secondary aircraft controller system:.

ABSTRACT OF THE DISCLOSURE

The present invention is a computer system designed to use the conventional devices and special programming of the present invention that will ensure the safe operation of aircraft. The present invention is an anti-terrorist and ~~anti-crash system~~Anti-Crash System to ensure and maintain complete control of an aircraft on the ground, during taxiing and even in the air. With the present invention in place, an aircraft can be kept a safe distance from any building and other aircraft, and the aircraft can be remotely controlled. The system provides greater national security. Utilizing the ~~on-demand~~On-Demand audio and visual monitoring components of the present invention, simultaneously, proper authorities can access all factual data from all onboard flight systems before a crash is imminent. Equipment lockouts are in place as well, so that if an aircraft is commandeered, the actual person in the cockpit is unable to effect aircraft travel, virtually eliminating human error.